


Historical Affairs and Landmark Review Board

Arlington County, Virginia



HALRB meeting April 20, 2022, Case 22-02


2204 N. Kenmore St.: Request to replace 14 wood windows with new wood windows.





















PIANO R.

29" RO

$28\frac{1}{2}$ " MO

28" FS

$22\frac{13}{64}$ " DLO



$29\frac{21}{64}$ " DLO

$35\frac{1}{8}$ " FS

$35\frac{3}{8}$ " MO

$35\frac{5}{8}$ " RO


3TH.FL.SIDE

24" RO

$23\frac{1}{2}$ " MO

23" FS

$17\frac{13}{64}$ " DLO



$17\frac{21}{64}$ " DLO

$23\frac{1}{8}$ " FS

$23\frac{3}{8}$ " MO

$23\frac{5}{8}$ " RO

3 TH.FL.FRONT

- Please see Figures 1-9 which show various photos of some of the windows on our existing home.
 - As part of CoA 15-17 (2015): DRC and HALRB previously approved 2 new “in-kind” windows on the historical portion of the house. One of the windows (bottom right in Figures 2 and 3) is basically an in-kind replacement (new) of the sister window (existing) to its left. We have included close up pictures to provide the Board with a clear understanding of just how similar these windows will be “in situ”.



Figure 1 - Main House



Figure 2 - Side view #1



Figure 3 - Side view #2



Figure 4 - Replacement Double Hung on Historical portion



Figure 5 -Existing Double Hung on Historical portion



Figure 6 - Side View B1



Figure 7 - Existing Double Hung



Figure 8 - Replacement Double Hung




Figure 9 - CoA 15-17 photos

<https://www.marvin.com/historic>

The screenshot shows the Marvin website's 'HISTORIC DESIGN SOLUTIONS' section. It features four project examples:

- HISTORIC MUSIC HALL RENOVATION**: An image of a large, ornate red brick building with multiple arched windows.
- CUSTOM GOTHIC REVIVAL CHURCH**: An image of a Gothic Revival church with tall, narrow arched windows and a steep roof.
- ST PAUL HISTORIC RENOVATION**: An image of a kitchen interior with white cabinets and a round dining table, featuring several large windows with white frames.
- UNION STABLES COMMERCIAL**: An image of a large, multi-story brick building with arched windows and a prominent gabled roof.

Each project has a 'LEARN MORE' button below its image.


The screenshot shows the Marvin website's 'EXPLORE HISTORIC DESIGN WINDOWS' section. It displays eight window models:

Window Type	Description
SIGNATURE Ultimate Double Hung G2	A vertical double-hung window with a grid pattern and a dark wood frame.
SIGNATURE Ultimate Double Hung Insert G2	A vertical double-hung window with a grid pattern and a light-colored wood frame.
SIGNATURE Ultimate Picture	A square picture window with a light-colored wood frame.
SIGNATURE Ultimate Specialty Shapes	A window with an irregular, curved shape, framed by a light-colored wood.
SIGNATURE Ultimate Wood Double Hung	A vertical double-hung window with a grid pattern and a light-colored wood frame.
SIGNATURE Ultimate Wood Double Hung Insert	A vertical double-hung window with a grid pattern and a light-colored wood frame.
SIGNATURE Ultimate Wood Double Hung Magnum	A tall vertical double-hung window with a grid pattern and a light-colored wood frame.
SIGNATURE Ultimate Wood Single Hung	A vertical single-hung window with a grid pattern and a light-colored wood frame.

Wood Ultimate Double Hung

Section Details: Operating


Scale: 3" = 1' 0"




Head Jamb and Sill

Double Hung

Lower Sash





Upper Sash




Jambs

Single Hung





Jambs




Head Jamb and Sill

Section Details: Operating and Stationary / Picture - 3/4" IG


Scale: 3" = 1' 0"




Standard Insulating Glass Divided Lite Options




Insulating Glass




Aluminum 11/16"
Contour GBG




3/4" Grille




1 1/8" Grille




5/8" SDL




5/8" SDL
W/Spacer




7/8" SDL




7/8" SDL
W/Spacer Bar




1 1/8" SDL




1 1/8" SDL
W/Spacer Bar




1 11/16" IG ADL




1 3/4" SDL




1 3/4" SDL
W/One Spacer Bar




1 3/4" SDL
W/Two Spacer Bars



2 13/32" SDL




2 13/32" SDL
W/One Spacer Bar




2 13/32" SDL
W/Two Spacer Bar


Ovolo



Square



Ogee



Executive Summary:

2204 N. Kenmore St., CoA 22-02 – David and Maria Greene

HALRB Board members,

Thanks again for your time and consideration with this project. After last meeting's discussion, we felt compelled to put together a summary of considerations in bullet point format:

Key reasons/considerations for replacement:

- Overall condition/Moisture issues/Restoration complexity and cost
 - Upon review of the photos from the original staff report of significant water/condensation/ice, it should be quite apparent that the windows have deteriorated, are deteriorating and will continue to do so.
 - Many articles/experts point to moisture being the primary cause of window deterioration. As several board members pointed out, even the 8-10 week restoration option will not solve the moisture issue because of the single pane glass. As even the restoration expert suggests, you would still have to add the storm windows which significantly adds to the cost and actually limits the ability to see the windows in situ.
 - An on-site repair will not fix the long-term deterioration, energy efficiency, health and cost challenges and should not be an option to consider or discuss.
 - Per summary of Mozer Works (one of the few restorers left in the area) discussion:
 - They would most likely have to take out each of the 14 windows to do offsite restoration. Mozer confirmed that the cost is equivalent to the cost of a new high end window. They also highly recommended storm windows (significant additional cost) even with the full restoration to maximize energy efficiency.
 - It takes 4-5 hours/window just to remove them and then the restoration process takes 8-10 weeks.
 - During the 8-10 week period, we would need plywood or plexiglass to cover window openings to keep out weather in a limited manner and avoid anyone falling out of the windows. Just having heavy plastic would create a safety hazard with someone potentially falling through.
 - For those 2.5 months, we are still attempting to LIVE in the house. The three bedrooms for our kids would have the covered window openings.
 - Please watch the 15 minute video to understand the complexity of the restoration process.
<http://windowrestoration.us/>
- Energy efficiency:
 - You can achieve better long term energy efficiency, reduce the overall carbon footprint and maintain the same visual from the street with in-kind replacement windows.
 - Restoration retains the single pane window which is the major cause for significant loss of heat and the devastating moisture damage.
 - Mozer confirms that the only way to come close to the energy efficiency of a double pained replacement window is to have a storm window installed in addition to the restored window which essentially covers up the original window and significantly adds to the cost.

- Health/Safety:
 - Mold/mildew and extremely low temperatures in the three bedrooms where children sleep can cause sickness and other health problems.
 - The temperature in the front room on the 1st floor and the front bedroom on the 2nd floor loses a significant amount of heat on extremely cold nights such that they are 5 -10 degrees colder than any other room.
 - Flies, stinkbugs, ladybugs infestations are 100% solved with the installation of in-kind replacement windows.
 - The 2 smaller dormer windows do not have any safety mechanisms to prevent them from opening all the way but are above a dormer bench with the possibility of someone falling out – a new replacement window will have the built in mechanisms to limit how far the window opens.
 - Many of the existing windows have a top sash that simply will not open limiting the ability to promote circulation/fresh air.
- Technical/Guideline considerations:
 - Per staff report, they cannot ascertain, even upon close examination, whether these windows actually date to the period of significance. There are no distinctive architectural features to confirm this and certainly no significant qualities from street view to suggest to a passerby whether they are or not.
 - There is no section and no language within the Maywood Guidelines which “**requires**” historic windows be repaired rather than replaced; it merely suggests they “**should**” be. The encouragement is understandable but there is no requirement. See snippet below.

Windows

Most Maywood houses have a single type and size of window for major openings, with smaller windows used as accents in gables, attics, and staircases. Repair or replacement of windows with different materials, a different design and/or a different size, requires a Certificate of Appropriateness. Vinyl or aluminum (or vinyl- or aluminum-clad) windows are inappropriate to Maywood. See the Secretary of the Interior’s Brief: [09: The Repair of Historic Wooden Windows](#)

Original windows should be repaired and restored.

- With the many references to the SOI standards themselves, we want to make sure the Board does not miss the guiding theme on the SOI website (see snippet below) which supports applying the standards in a “reasonable” manner taking into consideration economic and technical feasibility.

The Standards are to be applied to specific rehabilitation projects in a reasonable manner, taking into consideration economic and technical feasibility.

6. Deteriorated historic features shall be repaired rather than replaced. Where the severity of deterioration requires replacement of a distinctive feature, the new feature shall match the old in design, color, texture, and other visual qualities and, where possible, materials. Replacement of missing features shall be substantiated by documentary, physical, or pictorial evidence.
7. Chemical or physical treatments, such as sandblasting, that cause damage to historic materials shall not be used. The surface cleaning of structures, if appropriate, shall be undertaken using the gentlest means possible.
8. Significant archeological resources affected by a project shall be protected and preserved. If such resources must be disturbed, mitigation measures shall be undertaken.

- We also thought it important to highlight the introduction section of Maywood's Guidelines (most recently amended by the ACB in 2020) which provides an important context/lens through which Maywood residents/HALRB/HPP staff are encouraged to consider when weighing individual CoAs/projects on their own merits

4

6. Deteriorated historic features should be repaired rather than replaced. Where the severity of deterioration requires replacement of a distinctive feature, the new feature should match the old in design, color, texture, and, where possible, materials. Replacement of missing features should be substantiated by documentary and physical evidence.
7. Chemical or physical treatments, if appropriate, should be undertaken using the gentlest means possible. Treatments that cause damage to historic materials should not be used.
8. Archeological resources should be protected and preserved in place. If such resources must be disturbed, mitigation measures should be undertaken.
9. New additions, exterior alterations, or related new construction should not destroy historic materials, features, and spatial relationships that characterize the property.

The Maywood Guidelines are not intended to dictate architectural style or to require particular architectural features. Rather, they identify a range of design options which will encourage preservation and new development compatible with the existing character of the Maywood Historic District. In the design review process, economic feasibility, durability, design integrity and harmony of proposed improvements are all important concerns.

There is an important point to remember when using the guidelines: every house is unique. Even houses that look identical at first glance have details or characteristics that set them apart from others. This means that what is appropriate for one building may not be appropriate for another. Each building must be looked at on an individual basis both by the property owner and by the review board.

These guidelines were developed with the recognition that buildings are not static, but continue to evolve over time. These guidelines are not intended to prohibit changes, but rather to ensure that such changes are respectful of and compatible with the existing historic fabric and character of the neighborhood.

WOOD AWNING / WOOD AWNING PUSH OUT

MO (mm)	1 - 7 5/8 (498)	1 - 9 5/8 (549)	1 - 11 5/8 (600)	2 - 3 5/8 (702)	2 - 5 5/8 (752)	2 - 7 5/8 (803)	2 - 9 5/8 (854)	2 - 11 5/8 (905)	3 - 3 5/8 (1006)
RO (mm)	1 - 5 (431)	1 - 7 (482)	1 - 9 (533)	2 - 1 (635)	2 - 3 (685)	2 - 5 (736)	2 - 7 (787)	2 - 9 (838)	3 - 1 (939)
FS (mm)	1 - 4 (406)	1 - 6 (457)	1 - 8 (508)	2 - 0 (609)	2 - 2 (660)	2 - 4 (711)	2 - 6 (762)	2 - 8 (812)	3 - 0 (914)
DLO (mm)	0 - 11 19/64 (287)	1 - 1 19/64 (338)	1-3 19/64 (388)	1 - 7 19/64 (490)	1 - 9 19/64 (541)	1 - 11 19/64 (592)	2 - 1 19/64 (642)	2 - 3 19/64 (693)	2 - 7 19/64 (795)
	1 - 3 7/8 (403)	1 - 2 9/16 (370)	1 - 2 1/16 (357)	0 - 7 15/16 (186)					
	UWAWN 1614 UWAWNPO 1614	UWAWN 1814 UWAWNPO 1814	UWAWN 2014 UWAWNPO 2014	UWAWN 2414 UWAWNPO 2414	UWAWN 2614 UWAWNPO 2614	UWAWN 2814 UWAWNPO 2814	UWAWN 3014 UWAWNPO 3014	UWAWN 3214 UWAWNPO 3214	UWAWN 3614 UWAWNPO 3614
	1 - 5 7/8 (454)	1 - 4 9/16 (421)	1 - 6 1/16 (408)	0 - 9 15/16 (237)					
	UWAWN 1616 UWAWNPO 1616	UWAWN 1816 UWAWNPO 1816	UWAWN 2016 UWAWNPO 2016	UWAWN 2416 UWAWNPO 2416	UWAWN 2616 UWAWNPO 2616	UWAWN 2816 UWAWNPO 2816	UWAWN 3016 UWAWNPO 3016	UWAWN 3216 UWAWNPO 3216	UWAWN 3616 UWAWNPO 3616
	1 - 7 7/8 (505)	1 - 6 9/16 (471)	1 - 8 1/16 (522)	0 - 11 15/16 (287)					
	UWAWN 1618 UWAWNPO 1618	UWAWN 1818 UWAWNPO 1818	UWAWN 2018 UWAWNPO 2018	UWAWN 2418 UWAWNPO 2418	UWAWN 2618 UWAWNPO 2618	UWAWN 2818 UWAWNPO 2818	UWAWN 3018 UWAWNPO 3018	UWAWN 3218 UWAWNPO 3218	UWAWN 3618 UWAWNPO 3618
	1 - 9 7/8 (556)	1 - 8 9/16 (522)	1 - 10 1/16 (570)	0 - 11 15/16 (338)					
	UWAWN 1620 UWAWNPO 1620	UWAWN 1820 UWAWNPO 1820	UWAWN 2020 UWAWNPO 2020	UWAWN 2420 UWAWNPO 2420	UWAWN 2620 UWAWNPO 2620	UWAWN 2820 UWAWNPO 2820	UWAWN 3020 UWAWNPO 3020	UWAWN 3220 UWAWNPO 3220	UWAWN 3620 UWAWNPO 3620
	1 - 9 7/8 (657)	2 - 4 9/16 (725)	2 - 9 1/16 (624)	1 - 11 15/16 (440)					
	UWAWN 1624 UWAWNPO 1624	UWAWN 1824 UWAWNPO 1824	UWAWN 2024 UWAWNPO 2024	UWAWN 2424 UWAWNPO 2424	UWAWN 2624 UWAWNPO 2624	UWAWN 2824 UWAWNPO 2824	UWAWN 3024 UWAWNPO 3024	UWAWN 3224 UWAWNPO 3224	UWAWN 3624 UWAWNPO 3624
	2 - 5 7/8 (759)	2 - 4 9/16 (725)	2 - 11 1/16 (611)	1 - 13 15/16 (541)					
	UWAWN 1628 UWAWNPO 1628	UWAWN 1828 UWAWNPO 1828	UWAWN 2028 UWAWNPO 2028	UWAWN 2428 UWAWNPO 2428	UWAWN 2628 UWAWNPO 2628	UWAWN 2828 UWAWNPO 2828	UWAWN 3028 UWAWNPO 3028	UWAWN 3228 UWAWNPO 3228	UWAWN 3628 UWAWNPO 3628
	2 - 9 7/8 (860)	2 - 8 9/16 (827)	2 - 10 1/16 (814)	2 - 12 15/16 (643)					
	UWAWN 1632 UWAWNPO 1632	UWAWN 1832 UWAWNPO 1832	UWAWN 2032 UWAWNPO 2032	UWAWN 2432 UWAWNPO 2432	UWAWN 2632 UWAWNPO 2632	UWAWN 2832 UWAWNPO 2832	UWAWN 3032 UWAWNPO 3032	UWAWN 3232 UWAWNPO 3232	UWAWN 3632 UWAWNPO 3632
	3 - 1 7/8 (962)	3 - 2 9/16 (929)	3 - 3 1/16 (916)	2 - 5 15/16 (745)					
	UWAWN 1636 UWAWNPO 1636	UWAWN 1836 UWAWNPO 1836	UWAWN 2036 UWAWNPO 2036	UWAWN 2436 UWAWNPO 2436	UWAWN 2636 UWAWNPO 2636	UWAWN 2836 UWAWNPO 2836	UWAWN 3036 UWAWNPO 3036	UWAWN 3236 UWAWNPO 3236	UWAWN 3636 UWAWNPO 3636
	3 - 5 7/8 (1064)	3 - 4 9/16 (1030)	3 - 4 1/16 (1018)	2 - 9 15/16 (846)					
	UWAWN 1640 UWAWNPO 1640	UWAWN 1840 UWAWNPO 1840	UWAWN 2040 UWAWNPO 2040	UWAWN 2440 UWAWNPO 2440	UWAWN 2640 UWAWNPO 2640	UWAWN 2840 UWAWNPO 2840	UWAWN 3040 UWAWNPO 3040	UWAWN 3240 UWAWNPO 3240	UWAWN 3640 UWAWNPO 3640
	3 - 9 7/8 (1165)	3 - 8 9/16 (1132)	3 - 8 1/16 (1119)	3 - 1 15/16 (948)					
	UWAWN 1644 UWAWNPO 1644	UWAWN 1844 UWAWNPO 1844	UWAWN 2044 UWAWNPO 2044	UWAWN 2444 UWAWNPO 2444	UWAWN 2644 UWAWNPO 2644	UWAWN 2844 UWAWNPO 2844	UWAWN 3044 UWAWNPO 3044	UWAWN 3244 UWAWNPO 3244	UWAWN 3644 UWAWNPO 3644
	4 - 1 7/8 (1267)	4 - 9/16 (1233)	4 - 1/16 (1221)	3 - 5 15/16 (1049)					
	UWAWN 1648 UWAWNPO 1648	UWAWN 1848 UWAWNPO 1848	UWAWN 2048 UWAWNPO 2048	UWAWN 2448 UWAWNPO 2448	UWAWN 2648 UWAWNPO 2648	UWAWN 2848 UWAWNPO 2848	UWAWN 3048 UWAWNPO 3048	UWAWN 3248 UWAWNPO 3248	UWAWN 3648 UWAWNPO 3648















Details and Elevations not to scale.

- Ultimate Wood Awning Push Out not available in frame size heights greater than 48 $\frac{1}{16}$ ".
- For units with a tall bottom rail, reduce the DLO height by 1 $\frac{1}{2}$ ".

Ultimate Wood Awning: UWAWN

Ultimate Wood Awning Push Out: UWAWNPO

WOOD AWNING / WOOD AWNING PUSH OUT

MO (mm)	3 - 7 5/8 (1108)	4 - 3 5/8 (1311)	4 - 11 5/8 (1514)	5 - 3 5/8 (1616)	5 - 7 5/8 (1718)	6 - 3 5/8 (1921)
RO (mm)	3 - 5 (1041)	4 - 1 (1245)	4 - 9 (1448)	5 - 1 (1549)	5 - 5 (1651)	6 - 1 (1854)
FS (mm)	3 - 4 (1016)	4 - 0 (1219)	4 - 8 (1422)	5 - 0 (1524)	5 - 4 (1626)	6 - 0 (1829)
DLO (mm)	2 - 11 19/64 (896)	3 - 7 19/64 (1100)	4 - 3 19/64 (1303)	4 - 7 19/64 (1404)	4 - 11 19/64 (1506)	5 - 7 19/64 (1709)
1 - 3 7/8 (403)						
1 - 5 7/8 (454)						
1 - 6 9/16 (421)						
1 - 6 1/16 (459)						
1 - 8 1/16 (510)						
1 - 8 1/16 (611)						
1 - 1 15/16 (338)						
1 - 1 15/16 (643)						
2 - 9 7/8 (860)						
2 - 8 9/16 (827)						
2 - 8 1/16 (929)						
3 - 1 7/8 (1165)						
3 - 5 7/8 (1064)						
3 - 8 9/16 (1030)						
3 - 4 1/16 (1018)						
3 - 4 1/16 (916)						
2 - 9 15/16 (846)						
3 - 9 7/8 (1267)						
4 - 9/16 (1233)						
4 - 1/16 (1223)						
3 - 8 1/16 (1119)						
3 - 1 15/16 (948)						

Please consult your local Marvin representative for more information.
For further details and drawings visit the 'Tools and Documents' section at Marvin.com.

WOOD AWNING / WOOD AWNING PUSH OUT

MO (mm)	1 - 7 5/8 (498)	1 - 9 5/8 (549)	1 - 11 5/8 (600)	2 - 3 5/8 (702)	2 - 5 5/8 (752)	2 - 7 5/8 (803)	2 - 9 5/8 (854)	2 - 11 5/8 (905)	3 - 3 5/8 (1006)
RO (mm)	1 - 5 (431)	1 - 7 (482)	1 - 9 (533)	2 - 1 (635)	2 - 3 (685)	2 - 5 (736)	2 - 7 (787)	2 - 9 (838)	3 - 1 (939)
FS (mm)	1 - 4 (406)	1 - 6 (457)	1 - 8 (508)	2 - 0 (609)	2 - 2 (660)	2 - 4 (711)	2 - 6 (762)	2 - 8 (812)	3 - 0 (914)
DLO (mm)	0 - 11 19/64 (287)	1 - 1 19/64 (338)	1-3 19/64 (388)	1 - 7 19/64 (490)	1 - 9 19/64 (541)	1 - 11 19/64 (592)	2 - 1 19/64 (642)	2 - 3 19/64 (693)	2 - 7 19/64 (795)
	4 - 7 7/8 (1419) 4 - 6 9/16 (1386) 3 - 11 15/16 (1202)	4 - 9 7/8 (1470) 4 - 8 9/16 (1437) 4 - 8 1/16 (1424) 4 - 1 15/16 (1253)	5 - 1 7/8 (1572) 5 - 9/16 (1588) 5 - 1/16 (1526) 4 - 5 15/16 (1554)	5 - 5 7/8 (1673) 5 - 4 9/16 (1640) 5 - 4 1/16 (1627) 4 - 9 15/16 (1456)	5 - 1 7/8 (1676) 5 - 9/16 (1643) 5 - 1/16 (1630) 5 - 5 15/16 (1659)	5 - 1 7/8 (1676) 5 - 9/16 (1643) 5 - 1/16 (1630) 5 - 5 15/16 (1659)	5 - 1 7/8 (1676) 5 - 9/16 (1643) 5 - 1/16 (1630) 5 - 5 15/16 (1659)	5 - 1 7/8 (1676) 5 - 9/16 (1643) 5 - 1/16 (1630) 5 - 5 15/16 (1659)	5 - 1 7/8 (1676) 5 - 9/16 (1643) 5 - 1/16 (1630) 5 - 5 15/16 (1659)
	UWAWN 1654	UWAWN 1854	UWAWN 2054	UWAWN 2454	UWAWN 2654	UWAWN 2854	UWAWN 3054	UWAWN 3254	UWAWN 3654
	UWAWN 1656	UWAWN 1856	UWAWN 2056	UWAWN 2456	UWAWN 2656	UWAWN 2856	UWAWN 3056	UWAWN 3256	UWAWN 3656
	UWAWN 1660	UWAWN 1860	UWAWN 2060	UWAWN 2460	UWAWN 2660	UWAWN 2860	UWAWN 3060	UWAWN 3260	UWAWN 3660
	UWAWN 1664	UWAWN 1864	UWAWN 2064	UWAWN 2464	UWAWN 2664	UWAWN 2864	UWAWN 3064	UWAWN 3264	UWAWN 3664
	UWAWN 1672 T	UWAWN 1872 T	UWAWN 2072 T	UWAWN 2472 T	UWAWN 2672 T	UWAWN 2872 T	UWAWN 3072 T	UWAWN 3272 T	UWAWN 3672 T

Details and Elevations not to scale.

- Ultimate Wood Awning Push Out not available in frame size heights greater than 48 $\frac{1}{16}$ ".





















- For units with a tall bottom rail, reduce the DLO height by 1 1/2".

T For safety and/or code requirements, Marvin recommends tempered glass in all units with a frame size height of 72 $\frac{1}{16}$ " or larger and units with a frame size of 25.2 ft² and larger.

Please consult your local Marvin representative for more information.

For further details and drawings visit the 'Tools and Documents' section at Marvin.com.

WOOD AWNING / WOOD AWNING PUSH OUT

MO (mm)	3 - 7 5/8 (1108)	4 - 3 5/8 (1311)	4 - 11 5/8 (1514)	5 - 3 5/8 (1616)	5 - 7 5/8 (1718)	6 - 3 5/8 (1921)
RO (mm)	3 - 5 (1041)	4 - 1 (1245)	4 - 9 (1448)	5 - 1 (1549)	5 - 5 (1651)	6 - 1 (1854)
FS (mm)	3 - 4 (1016)	4 - 0 (1219)	4 - 8 (1422)	5 - 0 (1524)	5 - 4 (1626)	6 - 0 (1829)
DLO (mm)	2 - 11 19/64 (896)	3 - 7 19/64 (1100)	4 - 3 19/64 (1303)	4 - 7 19/64 (1404)	4 - 11 19/64 (1506)	5 - 7 19/64 (1709)
4 - 7 7/8 (1419) 4 - 6 9/16 (1386) 4 - 6 1/16 (1373) 3 - 11 15/16 (1202)						
UWAWN 4054	UWAWN 4854	UWAWN 5654	UWAWN 6054	UWAWN 6454	UWAWN 7254 T	
4 - 9 7/8 (1470) 4 - 8 1/16 (1437) 4 - 8 1/16 (1424) 4 - 1 15/16 (1253)						
UWAWN 4056	UWAWN 4856	UWAWN 5656	UWAWN 6056	UWAWN 6456	UWAWN7256 T	
5 - 1 7/8 (1572) 5 - 9/16 (1538) 5 - 1/16 (1526) 4 - 5 15/16 (1354)						
UWAWN 4060	UWAWN 4860	UWAWN 5660	UWAWN 6060	UWAWN 6460 T	UWAWN 7260 T	
5 - 5 7/8 (1673) 5 - 4 9/16 (1640) 5 - 4 1/16 (1627) 4 - 9 15/16 (1456)						
UWAWN 4064	UWAWN 4864	UWAWN 5664	UWAWN 6064 T	UWAWN 6464 T	UWAWN 7264 T	
6 - 1 7/8 (1876) 6 - 9/16 (1843) 6 - 1/16 (1830) 5 - 5 15/16 (1659)						
UWAWN 4072 T	UWAWN 4872 T	UWAWN 5672 T	UWAWN 6072 T	UWAWN 6472 T	UWAWN 7272 T	

WOOD DOUBLE HUNG

MO (mm)	2-0 1/2 (622)	2-4 1/2 (724)	2-8 1/2 (826)	2-10 1/2 (876)	3-0 1/2 (927)	3-2 1/2 (978)	3-4 1/2 (1029)	3-8 1/2 (1130)	4-0 1/2 (1232)
RO (mm)	1-10 3/8 (568)	2-2 3/8 (670)	2-6 3/8 (772)	2-8 3/8 (822)	2-10 3/8 (873)	3-0 3/8 (924)	3-2 3/8 (975)	3-6 3/8 (1076)	3-10 3/8 (1178)
FS (mm)	1-9 3/8 (543)	2-1 3/8 (645)	2-5 3/8 (746)	2-7 3/8 (797)	2-9 3/8 (848)	2-11 3/8 (899)	3-1 3/8 (949)	3-5 3/8 (1051)	3-9 3/8 (1153)
DLO (mm)	1-2 15/16 (379)	1-6 15/16 (481)	1-10 15/16 (583)	2-0 15/16 (633)	2-2 15/16 (684)	2-4 15/16 (735)	2-6 15/16 (786)	2-10 15/16 (887)	3-2 15/16 (989)
	UWDH1612	UWDH2012	UWDH2412	UWDH2612	UWDH2812	UWDH3012	UWDH3212	UWDH3612	UWDH4012
	UWDH1614	UWDH2014	UWDH2414	UWDH2614	UWDH2814	UWDH3014	UWDH3214	UWDH3614	UWDH4014
	UWDH1616	UWDH2016	UWDH2416	UWDH2616	UWDH2816	UWDH3016	UWDH3216	UWDH3616	UWDH4016
	UWDH1618	UWDH2018	UWDH2418	UWDH2618	UWDH2818	UWDH3018	UWDH3218	UWDH3618	UWDH4018
	UWDH1620	UWDH2020	UWDH2420	UWDH2620	UWDH2820	UWDH3020	UWDH3220	UWDH3620	UWDH4020
	UWDH1622	UWDH2022	UWDH2422	UWDH2622	UWDH2822	UWDH3022	UWDH3222	UWDH3622	UWDH4022
	UWDH1624	UWDH2024	UWDH2424	UWDH2624	UWDH2824	UWDH3024	UWDH3224	UWDH3624	UWDH4024
	UWDH1626	UWDH2026	UWDH2426	UWDH2626	UWDH2826	UWDH3026	UWDH3226	UWDH3626 E	UWDH4026 E
	UWDH1628	UWDH2028	UWDH2428	UWDH2628	UWDH2828	UWDH3028 E	UWDH3228 E	UWDH3628 E	UWDH4028 E

MULTIPLE ASSEMBLY CONVERSIONS

ROUGH OPENING		MASONRY OPENING WITH BMC	
Width	Height	Width	Height
Add all frame sizes	Add frame sizes plus 1" (25)	Add all frame sizes plus 3 1/8" (79)	Add frame sizes plus 1 9/16" (39)
5-6 9/16 (1691) 5-5 1/2 (1664) 5-5 5 (1651) 2-2 15/16 (684)	4-10 9/16 (1488) 4-9 1/2 (1461) 4-9 (1448) 1-10 15/16 (583)	4-6 9/16 (1386) 4-5 1/2 (1359) 4-5 (1346) 1-8 15/16 (532)	2-10 9/16 (1284) 3-9 1/2 (1257) 3-9 (1143) 1-2 15/16 (481)

Details and Elevations not to scale.

E These windows meet national Egress codes for fire evacuation. Local codes may differ.

* For more Cottage Style sizes than the sample shown, please contact your Marvin representative. Ultimate Double Hung cottage call number formula is figured in fifths. Top sash is $\frac{2}{5}$ and bottom is $\frac{3}{5}$.

1. Standard call number; 2024
2. Add the two glass heights; $24" + 24" = 48"$
3. Divide 48" by $\frac{2}{5}$; $19\frac{1}{2}$ /64"
4. Round to the nearest standard glass height; 20"
5. Subtract from total glass height; $48" - 20" = 28"$ The call number for the above example is: 2020/28. The top sash will be a 2020 and the bottom sash will be a 2028

Ultimate Wood Double Hung: UWDH

WOOD DOUBLE HUNG

MO (mm)	2-0 1/2 (622)	2-4 1/2 (724)	2-8 1/2 (826)	2-10 1/2 (876)	3-0 1/2 (927)	3-2 1/2 (978)	3-4 1/2 (1029)	3-8 1/2 (1130)	4-0 1/2 (1232)
RO (mm)	1-10 3/8 (568)	2-2 3/8 (670)	2-6 3/8 (772)	2-8 3/8 (822)	2-10 3/8 (873)	3-0 3/8 (924)	3-2 3/8 (975)	3-6 3/8 (1076)	3-10 3/8 (1178)
FS (mm)	1-9 3/8 (543)	2-1 3/8 (645)	2-5 3/8 (746)	2-7 3/8 (797)	2-9 3/8 (848)	2-11 3/8 (899)	3-1 3/8 (949)	3-5 3/8 (1051)	3-9 3/8 (1153)
DLO (mm)	1-2 15/16 (379)	1-6 15/16 (481)	1-10 15/16 (583)	2-0 15/16 (633)	2-2 15/16 (684)	2-4 15/16 (735)	2-6 15/16 (786)	2-10 15/16 (887)	3-2 15/16 (989)
	5-10 9/16 (1792)	5-9 1/2 (1165)	5-9 3/8 (1153)	24 15/16 (736)					
	UWDH1630	UWDH2030	UWDH2430	UWDH2630	UWDH2830 E	UWDH3030 E	UWDH3230 E	UWDH3630 E	UWDH4030 E
	5-2 9/16 (1894)	6-1 1/2 (1887)	6-1 (1854)	2-6 15/16 (786)					
	UWDH1632	UWDH2032	UWDH2432	UWDH2632 E	UWDH2832 E	UWDH3032 E	UWDH3232 E	UWDH3632 E	UWDH4032 E
	6-6 9/16 (1996)	6-5 1/2 (1989)	6-5 (1956)	2-8 15/16 (837)					
	UWDH1634	UWDH2034	UWDH2434 E	UWDH2634 E	UWDH2834 E	UWDH3034 E	UWDH3234 E	UWDH3634 E	UWDH4034 E
	6-10 9/16 (2097)	6-9 1/2 (2070)	6-9 (2057)	2-10 15/16 (887)					
	UWDH1636	UWDH2036	UWDH2436 E	UWDH2636 E	UWDH2836 E	UWDH3036 E	UWDH3236 E	UWDH3636 E	UWDH4036 E
	7-6 9/16 (2300)	7-5 1/2 (2273)	7-5 (2261)	3-2 15/16 (989)					
	UWDH1640	UWDH2040	UWDH2440 E	UWDH2640 E	UWDH2840 E	UWDH3040 E	UWDH3240 E	UWDH3640 E	UWDH4040 E
	7-10 9/16 (2402)	7-9 1/2 (2375)	7-9 (2362)	3-4 15/16 (1040)					
	UWDH1642	UWDH2042	UWDH2442 E	UWDH2642 E	UWDH2842 E	UWDH3042 E	UWDH3242 E	UWDH3642 E	UWDH4042 E

COTTAGE STYLE*

MO (mm)	2-0 1/2 (622)	2-4 1/2 (724)	2-8 1/2 (826)	2-10 1/2 (876)	3-0 1/2 (927)	3-2 1/2 (978)	3-4 1/2 (1029)	3-8 1/2 (1130)	4-0 1/2 (1232)
RO (mm)	1-10 3/8 (568)	2-2 3/8 (670)	2-6 3/8 (772)	2-8 3/8 (822)	2-10 3/8 (873)	3-0 3/8 (924)	3-2 3/8 (975)	3-6 3/8 (1076)	3-10 3/8 (1178)
FS (mm)	1-9 3/8 (543)	2-1 3/8 (645)	2-5 3/8 (746)	2-7 3/8 (797)	2-9 3/8 (848)	2-11 3/8 (899)	3-1 3/8 (949)	3-5 3/8 (1051)	3-9 3/8 (1153)
DLO (mm)	1-2 15/16 (379)	1-6 15/16 (481)	1-10 15/16 (583)	2-0 15/16 (633)	2-2 15/16 (684)	2-4 15/16 (735)	2-6 15/16 (786)	2-10 15/16 (887)	3-2 15/16 (989)
	5-10 9/16 (1792)	5-9 1/2 (1165)	5-9 3/8 (1153)	1-10 15/16 (583) / 2-10 15/16 (887)					
	UWDH1624/36	UWDH2024/36	UWDH2424/36	UWDH2624/36	UWDH2824/36	UWDH3024/36	UWDH3224/36	UWDH3624/36	UWDH4024/36

Please consult your local Marvin representative for more information.
For further details and drawings visit the 'Tools and Documents' section at Marvin.com.