



foot setback (Zoning Administrator) g the ACZO, of 31A.E.3 SS to Pursuaņt γd GRANTED

yard has been

(date)


uo















......

.

,

WEIT SIDE





и К

Huson-Braghetta Back Porch Screening 2101 North Kenmore St, November 2022

Purpose of request is to screen existing rectangular back porch (Note: back porch has only one corner column).

No demolition involved - NA

Description of work: Screening of Small Back porch only:

- 1) Frame and install screening around porch with single corner column. Screen framing will be fully scribed to single corner column profile to reveal column shape including Crown and Foot molding. Corner column will be exposed and fully visible to external view, exposing 210 ° of corner column visible to external view on southeast corner of home. Column will not be enclosed by screening.
- 2) Install inswing swinging screen door (36" x 80") according to submitted drawings.

Materials:

- Screen door—Inswing, swinging screen storm door (Anderson or equivalent).
- Screening framework— Will be constructed of wood framing, per architectural drawings that will be drawn up by Frank Durkin, same architect that drafted drawings for screen porch at corner 22nd St & Monroe. (see photo below).
- Screening material —As recommended by architect.



Photos of existing back porch, 2101 N Kenmore St.


MAN JAVA-K



Comparable Screen Porches from around the Maywood Neighborhood



22nd St. & Monroe








21 st Ave near Kenmore



21st Ave & Kenmore St






West

Existing inswing door to kitchen

North

House wall

East



Existing inswing door to kitchen

> North House wall

NEW SCREEN PORCH ELEMENTS HIGHLIGHTED IN GREEN & ITALICS