
# Reeves Farmhouse Renovation Concept DRC Submission

April, 2023



# Table of Contents:

Cover1
Existing Conditions - Site2-3
Existing Conditions - Building4-8
Site Plan9
3D Views10-14
Ramp Options15-16
Demolition and Proposed Plans17-21
Elevations22-23



Cover



#### Source: Google Earth


#### Reeves Farmhouse














Existing Site Conditions Reeves Farmhouse














Arlington County URD Plan



#### Reeves Farmhouse





WASHINGTON, D.C.


& Northern Virginia


# Historic Evolution Plans

Source: "An Historical, Architectural, and Archeological Survey Torreyson-Reeves Farm" by John Milner Associates, May, 2004.



# Reeves Farmhouse














o 4 8

Existing First Floor

16 FT

 $\bigotimes$ 

5









# Reeves Farmhouse












































Existing Third Floor Reeves Farmhouse

7


16 FT

0 4 8





luating the project feasibility, reliminary in nature. derations may yield differing



0 4 8



& Northern Virginia

Existing Cellar and Roof Plans

16 FT


 $\bigotimes$ 

8





#### Reeves Farmhouse





#### Reeves Farmhouse



L'ARCHE GREATER WASHINGTON, D.C.

10






Proposed Alternate 1

Proposed Alternate 2




Existing and Proposed 3D Views


11



View from NW

#### Reeves Farmhouse






Proposed Alternate 1

Proposed Alternate 2




Existing and Proposed 3D Views

12



#### View from SE

#### Reeves Farmhouse



Existing

Proposed Alternate 2




Massing Study

13

# Alternate Option 2

# Reeves Farmhouse









Massing Study

14



# Alternate Option 2


## Reeves Farmhouse





BEDROOM 5

140 SF



BEDROOM 3

109 SE

CL

DO

٦

HOIST SY

 $\bigcirc$ 

BEDROOM 4


107 SI

52' - 8 3/4"

WIC



**Entrance View** 



## Reeves Farmhouse






EMR

BEDROOM 5

140 SF

ELEV



BEDROOM 3

109 SE

CL

 $\mathcal{D}$ 

 $^{\circ}$ 

HC BATH

 $\bigcirc$ 

HOIST SYST


BEDROOM 4

52" - 8 3/4"

WIC





**Entrance View** 





# Reeves Farmhouse







Demolition and Proposed Cellar Plans



Area Summary			
<u>Floor</u>	<u>Existing</u> <u>Area</u> ( <u>gsf)</u>	<u>Addition</u> <u>Area</u> ( <u>gsf)</u>	<u>Total</u> <u>Area</u> ( <u>gsf)</u>
Cellar	367	0	367
1st Floor	1,382	1,312	2,694
2nd Floor	1,293	370	1,663
3rd Floor	351	0	351
Total	3,393	1,682	5,075

## Legend

[		1
·	 	 · -


Existing to remain


Existing to be demolished

New Construction

# Alternate Option 2

#### Reeves Farmhouse







Demolition and Proposed 1st Floor Plans



Area Summary			
<u>Floor</u>	<u>Existing</u> <u>Area</u> ( <u>gsf)</u>	<u>Addition</u> <u>Area</u> ( <u>gsf)</u>	<u>Total</u> <u>Area</u> ( <u>gsf)</u>
Cellar	367	0	367
1st Floor	1,382	1,312	2,694
2nd Floor	1,293	370	1,663
3rd Floor	351	0	351
Total	3,393	1,682	5,075

## Legend

[		1
·	 	 · -


Existing to remain


Existing to be demolished

New Construction

# Alternate Option 2

#### Reeves Farmhouse







Demolition and Proposed 2nd Floor Plans



Area Summary			
<u>Floor</u>	<u>Existing</u> <u>Area</u> ( <u>gsf)</u>	<u>Addition</u> <u>Area</u> ( <u>gsf)</u>	<u>Total</u> <u>Area</u> ( <u>gsf)</u>
Cellar	367	0	367
1st Floor	1,382	1,312	2,694
2nd Floor	1,293	370	1,663
3rd Floor	351	0	351
Total	3,393	1,682	5,075

## Legend

[		1
·	 	 · -


Existing to remain


Existing to be demolished

New Construction

## Alternate Option 2

#### Reeves Farmhouse







Demolition and Proposed Attic Floor Plans



Area Summary			
<u>Floor</u>	<u>Existing</u> <u>Area</u> ( <u>gsf)</u>	<u>Addition</u> <u>Area</u> ( <u>gsf)</u>	<u>Total</u> <u>Area</u> ( <u>gsf)</u>
Cellar	367	0	367
1st Floor	1,382	1,312	2,694
2nd Floor	1,293	370	1,663
3rd Floor	351	0	351
Total	3,393	1,682	5,075

## Legend

[		1
·	 	 · -


Existing to remain

Existing to be demolished

New Construction

## Alternate Option 2

#### Reeves Farmhouse





Demolition and Proposed Roof Plans




# Legend


	Existing to remain
[]	Existing to be demolished
	New Construction

# Alternate Option 2


#### Reeves Farmhouse



2. West Elevation



1. North Elevation





WASHINGTON DC

#### Material Legend


- 1. Remove existing vinyl/aluminum siding and trim. Inspect and report on condition of existing wood siding and trim below, if any.
- 2. Restore existing wood siding and trim. Patch, repair, and or replace to match as required. Prepare to receive new paint. If condition of existing siding is badly deteriorated, provide new wood clapboard siding to match existing profiles.
- 3. Remove existing asphalt shingles and provide new dimensional asphalt shingles. Provide new gutters and downspouts.
- 4. Remove existing metal roofing and provide new dimensional asphalt shingles. Provide new gutters and downspouts.
- 5. Remove existing brick chimneys down to roof line and rebuild. Provide new flagstone cap.
- 6. Remove existing front porch flooring and inspect existing joists. Repair/ replace joists as required.
- Remove existing door and provide new 36" wide 4-panel solid wood exterior door with lite. Finish to be painted. Provide lever type accessible hardware with deadbolt.
- 8. Remove existing windows and provide prefinished aluminum-clad wood double hung windows in 1-over-1 lite pattern. Provide with insulated low-e glazing, including argon gas fill.
- Remove existing windows and provide prefinished aluminum-clad wood double hung windows in 6-over-6 lite pattern. Provide with insulated low-e glazing, including argon gas fill.
- 10. New dimensional asphalt shingles. Provide prefinished aluminum gutters and downspouts.
- 11. New prefinished fiber cement lap-siding with fiber cement or PVC trim.
- 12. 36" wide 4-panel solid wood exterior door with lite.
- 13. New prefinished aluminum-clad wood double-hung windows in 1-over-1 lite pattern.

#### Alternate Option 2

#### **Reeves Farmhouse**



4. East Elevation







#### Material Legend

- Remove existing vinyl/aluminum siding and trim. Inspect and report on condition of existing wood siding and trim below, if any.
- 2. Restore existing wood siding and trim. Patch, repair, and or replace to match as required. Prepare to receive new paint. If condition of existing siding is badly deteriorated, provide new wood clapboard siding to match existing profiles.
- 3. Remove existing asphalt shingles and provide new dimensional asphalt shingles. Provide new gutters and downspouts.
- 4. Remove existing metal roofing and provide new dimensional asphalt shingles. Provide new gutters and downspouts.
- 5. Remove existing brick chimneys down to roof line and rebuild. Provide new flagstone cap.
- 6. Remove existing front porch flooring and inspect existing joists. Repair/ replace joists as required.
- Remove existing door and provide new 36" wide 4-panel solid wood exterior door with lite. Finish to be painted. Provide lever type accessible hardware with deadbolt.
- 8. Remove existing windows and provide prefinished aluminum-clad wood double hung windows in 1-over-1 lite pattern. Provide with insulated low-e glazing, including argon gas fill.
- Remove existing windows and provide prefinished aluminum-clad wood double hung windows in 6-over-6 lite pattern. Provide with insulated low-e glazing, including argon gas fill.
- 10. New dimensional asphalt shingles. Provide prefinished aluminum gutters and downspouts.
- 11. New prefinished fiber cement lap-siding with fiber cement or PVC trim.
- 12. 36" wide 4-panel solid wood exterior door with lite.
- 13. New prefinished aluminum-clad wood double-hung windows in 1-over-1 lite pattern.

#### Alternate Option 2

#### **Reeves Farmhouse**