



BARCROFT APARTMENTS PHASE II REHABILITATION

INCLUDING ALTERATIONS

SECTION 4 BUILDINGS 32-34

1130 S GEORGE MASON DR. ARLINGTON, VA 22204

HALRB SUBMISSION

SEPTEMBER 13, 2023

OWNER/CLIENT

JAIR LYNCH REAL ESTATE PARTNERS 1400 16th St NW, Suite 430 Washington, DC 20036

LAND-USE ATTORNEY

WALSH COLUCCI LUBELEY & WALSH 2200 Clarendon Boulevard, Suite 1300 Arlington, Virginia 22201

ARCHITECT

BONSTRA | HARESIGN ARCHITECTS 1728 14th Street NW, Suite 300 Washington, DC 20009

CIVIL ENGINEER

VIKA VIRGINIA, LLC. 8180 Greensboro Dr., Suite 200 Tysons, VA 22102

HISTORIC PRESERVATION


EHT TRACERIES, INC.
440 Massachusetts Avenue
Washington, DC 20001

SHEET INDEX

SITE AERIAL	3
DEVELOPMENT HISTORY	4
EXISTING SITE PLAN	5
EXISTING CONDITIONS PHOTOGRAPHS	6
EXISTING CONDITIONS PHOTOGRAPHS - BUILDING 32 EXISTING CONDITIONS PHOTOGRAPHS - BUILDING 33 EXISTING CONDITIONS PHOTOGRAPHS - BUILDING 34	7
DESCRIPTION OF WORK	9
DEMOLITION ELEVATIONS	10
BUILDING 32	10
BUILDING 33	14
BUILDING 34	17
BUILDING 33 - ADA MODIFICATIONS	19
SITE PLAN	19
TREE REMOVAL EXHIBIT	20
PROPOSED PLAN	21
PROPOSED ELEVATION - RAILING OPTION #1	22
PERSPECTIVE VIEW - RAILING OPTION #1	23
PROPOSED ELEVATION - RAILING OPTION #1	24
PERSPECTIVE VIEW - RAILING OPTION #2	25
RAILING OPTION PRECEDENT IMAGES	
NEW REAR ENTRY DOORS AT ACCESSIBLE ENTRIES	27


.3	WINDOW REPLACEMENTS	28
.4	EXTERIOR LIGHT FIXTURE REPLACEMENTS	29
.5	VHDA MCDR - ENTRY CANOPIES	30
	FRONT ENTRY - OPTION 1	30
.6	FRONT ENTRY - OPTION 2	.31
6	REAR ENTRY	32
7		
Ω	VHDA MCDR - TRIM AND FASCIA CLADDING	33

SITE AERIAL **BARCROFT PHASE II REHABILITATION**





BARCROFT PHASE II REHABILITATION DEVELOPMENT HISTORY



EXISTING SITE PLAN BARCROFT PHASE II REHABILITATION




































BARCROFT PHASE II REHABILITATION DESCRIPTION OF WORK

Scope of Work

The proposed project involves the rehabilitation of five existing buildings (Buildings 32a, 32b, 33a, 33b, and 34) located within Barcroft Section 4. The buildings will be rehabilitated consistent with the Arlington County Conservation Area Standards, which are based upon the Secretary of the Interior's Standards for Rehabilitation. The project must also adhere to the Virginia Housing Minimum Design and Construction Requirements (MDCR).

The project scope of work includes:

- Repair of exterior masonry (including brick and cast stone); Repoint deteriorated mortar where necessary matching the existing size, shape, color, and texture
- Gently clean and wash all existing brick and concrete facades with low- to medium-pressure adhering to the Secretary of the Interior's Standards and "NPS Preservation Brief #1: Assessing Cleaning and Water-Repellent Treatments for Historic Masonry Buildings"
- Removal and replacement of steel-sash basement windows matching the original configuration. All new windows proposed to be vinyl to match existing adjacent windows*
- Removal and replacement of existing mechanical systems including existing through-wall mechanical system openings. Patch exterior wall to match surrounding brick.
- Removal and replacement of non-original light fixtures with new compatible fixtures
- · Replacement of gutters and downspouts in-kind
- · Replacement of asphalt roofs with new asphalt
- Repair and paint existing metal railings
- · Repair and paint existing non-original shutters
- Repair and paint corroded metal lintels
- Addition of ADA ramps and entrances at rear elevation of Building 33
- Addition of new entry canopy above entrances to meet Virginia Housing MCDRs*
- Addition of vinyl or aluminum cladding on existing wood trim per Virginia Housing MDCRs*
- Addition of new penetrations on rear elevations for bathroom exhaust, dryer, and HVAC vents*
- * Conservation Area standard modification necessary in order to meet MDCR requirements.














BARCROFT PHASE II REHABILITATION BUILDING 32 - ELEVATIONS A-A1



© 2023 - Bonstra | Haresign Architects

BARCROFT PHASE II REHABILITATION


BUILDING 32 - ELEVATIONS B-C



© 2023 - Bonstra | Haresign Architects

BARCROFT PHASE II REHABILITATION

BUILDING 32 - ELEVATIONS C1-D



BUILDING 32 - ELEVATIONS D1 BARCROFT PHASE II REHABILITATION



GENERAL DEMOLITION ELEVATION NOTES

BUILDING 32 - ELEVATION D1 - DEMOLITION

- REPOINT DETERORIATED MORTAR TO MATCH ENSTING (TYPE, COLOR, COMPOSITION, AND TOOLING) WHERE NECESSARY;
 REMOVE ABANDONED TEMS AND SAL VASE REMOVED BRICKS FOR REUSE;
 REMOVE DAMAGED WINDOW SHUTTERS, TYP;
 GENTLY CLEAP AND WORSH ALL EXISTING BRICK AND CONCRETE FACADES WITH LOW-TO-MEDIUM PRESSURE. START WITH A VERY LOW PRESSURE (100PS) OR BELOW) AND PROGRESS AS NEEDED TO SUCHTLY HIGHER PRESSURE NOT TO EXCEED 300-400PSI. ALL EXTERIOR CLEANING TO BE UNDERTAKEN USING THE GENULES THANSP DOSSINE. TO ADHERE TO THE SECRETARY OF THE METRIOR'S STANDARDS AND INPS PRESERVATION BRIEF#1: ASSESSING CLEANING AND WATER-REPELLANT TREATMENTS FOR HISTORIC MASONRY BUILDINGS.
 ALL WINDOWS OLDER THAN 25 YEARS MUST BE REMOVED.
 PREPARE EXISTING RAILING TO BE PAINTED.
 CLEAN AND WASH ALL EXISTING WINDOW WELLS. REFER TO NOTE #4;

KEYED DEMOLITION ELEVATION NOTES EXISTING BRICK, CONCRETE AND TRIM TO REMAIN, TYP;

- EXISTING BRICK, CONCRETE AND TRIM TO REMAIN, TIP;

 EXISTING WINDOWS TO REMAIN, TIP;

 EXISTING WINDOWS TO REMAIN, TIP;

 EXISTING BUILDING EXTERIOR ENTRY DOORS TO REMAIN, REPAIR AS NECESSARY, TYP;

 BERMOVE EXISTING DAMAGED ROOF SLATE TILESSHINGLES AND ASSOCIATED UNDERLAYMENT AND FLASHING WHERE NECESSARY, TYP;

 REMOVE EXISTING GUTTER AND DOWNSPOUT WHERE DAMAGED BEYOND REPAIR, TYP;

 EXISTING ATTIC VENTS TO REMAIN, TYP;

 EXISTING STRENGRICH CHAPT KINDLES TO BE REMOVED, TYP;

 EXISTING STRENGRICH FOR THE PEPARE TO RECEIVE NEW PAINT;

 EXISTING SHUTTERS TO REMAIN, REPAIR AS NECESSARY, PREPARE TO RECEIVE NEW PAINT, TYP;

 EXISTING SHUTTERS TO REMAIN, REPAIR AS NECESSARY, PREPARE TO RECEIVE NEW PAINT, TYP;

 EVISTING RAIL ING TO REMAIN, REPAIR AS NECESSARY, PREPARE TO RECEIVE NEW PAINT, TYP;

 EVISTING AND TO TREMAIN PROPARE TO RECEIVE NEW PAINT.

(12)	EXISTING RAILING TO BE DEMOLISHED;
1213	REMOVE EXISTING WINDOWS;

BARCROFT PHASE 2&3 - SECTION ARLINGTON COUNTY, VIRGINIA **DRAWING LEGEND** NEW ELEMENT ===== EXISTING ELEMENT TO BE REMOVED BUILDING 32 - ELEVATIONS - DEMOLITION BASE BUILDING / EXISTING ELEMENT TO REMAIN DRAWING SET NOT FOR CONSTRUCTION AD0212

13

Bonstra Haresign

ww.bonstra.com 202 588 9373 T

ARCHITECTS

JAIR LYNCH REAL ESTATE PARTNERS

VIKA VIRGINIA. LLC

SII MAN & 1053 31ST STREET NW WASHINGTON, DC 20007 (202) 336 6230


SUMMIT ENGINEERS

BARCROFT PHASE II REHABILITATION BUILDING 33 - ELEVATIONS A-B




© 2023 - Bonstra | Haresign Architec

BUILDING 33 - ELEVATIONS C-C1 BARCROFT PHASE II REHABILITATION







BUILDING 33 - ELEVATION C1 - DEMOLITION

GENERAL DEMOLITION ELEVATION NOTES

- REPOINT DETERORIATED MORTAR TO MATCH EXISTING (TYPE, COLOR, COMPOSITION, AND TOOLING) WHERE NECESSARY, REMOVE ABANDONED ITEMS AND SALVAGE REMOVED BRICKS FOR REUSE; REMOVE DAMAGED WINDOW SHUTTERS, TYP: GENITY CLEAN AND WASH ALL DISTING BRICK AND CONCRETE FACADES WITH LOW-TO-MEDIUM PRESSURE. START WITH A VERY LOW PRESSURE (100PSI

- GRELOW, AND PROGRESS AS RECEIVED TO SLIGHTLY HIGHER PRESSURE; HIGHER HOLD AND AND PROGRESS AS RECEIVED TO SLIGHTLY HIGHER PRESSURE; HIGHER HOLD TO EXCEED 304-40/PSI. ALL EXTENDED, CLEANING TO BE UNDERTAKEN USING THE GENTLEST MEMBER DOSSIBLE TO A DIFFER TO THE SCORETAKY OF THE INTERIOR'S STANDARDS AND INPS PRESERVATION BRIEFFI; ASSESSING CLEANING AND WATER-REPELLANT TREATMENTS FOR INSTORIC MASONRY BUILDINGS.

 ALL WINDOWS OLDER THAN 25 YEARS MUST BE REMOVED.

 PREPARE SIXTING RAILHOT DOE PAINTED.

 CLEAN AND WASH ALL EXISTING WINDOW WELLS, REFER TO NOTE #4;

KEYED DEMOLITION ELEVATION NOTES

EXISTING BRICK, CONCRETE AND TRIM TO REMAIN, TYP;

EXISTING BRICK, CONCRETE AND TRIM TO REMAIN, TYP;

EXISTING BRUNDING EXTERIOR ENTRY DOORS TO REMAIN, REPAIR AS NECESSARY, TYP;

EXISTING BRUNDING EXTERIOR ENTRY DOORS TO REMAIN, REPAIR AS NECESSARY, TYP;

REMOVE ALE DESIGNED EXTERIOR HAVE COURTHENT, TYP;

REMOVE EXISTING CONTROL OF SAITE IT LESSISSANCES AND ASSOCIATED UNDERLAYMENT AND FLASHING WHERE NECESSARY, TYP;

REMOVE EXISTING GUTTER AND DOWNSPOUT WHERE DAMAGED BEYOND REPAIR, TYP;

EXISTING EXTERIOR LIGHT FIXTURES TO BE REMOVED, TYP;

EXISTING EXTERIOR LIGHT FIXTURES TO BE REMOVED, TYP;

EXISTING EXTERIOR TIME TO REMAIN, PREPAIR TO RECEIVE NEW PAINT;

EXISTING FAILING TO REMAIN, PREPAIR TO RECEIVE NEW PAINT;

EXISTING SHITTERS TO BE DEMAILSHED;

REMOVE EXISTING PRINTS TO BE DEMAILSHED;

REMOVE EXISTING PRINTS WINDOWS;

DRAWING LEGEND

BASE BUILDING / EXISTING ELEMENT TO REMAIN


NEW ELEMENT ===== EXISTING ELEMENT TO BE REMOVED

JAIR LYNCH REAL ESTATE PARTNERS VIKA VIRGINIA. LLC SII MAN & 1053 31ST STREET NW WASHINGTON, DC 2000 (202) 336 6230 SUMMIT ENGINEERS BARCROFT PHASE 2&3 - SECTION ARLINGTON COUNTY, VIRGINIA BUILDING 33 - ELEVATIONS -DEMOLITION DRAWING SET NOT FOR CONSTRUCTION AD0214


Bonstra Haresign

ARCHITECTS

BUILDING 33 - ELEVATIONS D-D1 BARCROFT PHASE II REHABILITATION



BUILDING 33 - ELEVATION D - DEMOLITION



BUILDING 33 - ELEVATION D1 - DEMOLITION

GENERAL DEMOLITION ELEVATION NOTES

- REPOINT DETERORIATED MORTAR TO MATCH ENSTING (TYPE, COLOR, COMPOSITION, AND TOOLING) WHERE NECESSARY;
 REMOVE ABANDONED TEMS AND SAL VASE REMOVED BRICKS FOR REUSE;
 REMOVE DAMAGED WINDOW SHUTTERS, TYP;
 GENTLY CLEAP AND WORSH ALL EXISTING BRICK AND CONCRETE FACADES WITH LOW-TO-MEDIUM PRESSURE. START WITH A VERY LOW PRESSURE (100PS) OR BELOW) AND PROGRESS AS NEEDED TO SUCHTLY HIGHER PRESSURE NOT TO EXCEED 300-400PSI. ALL EXTERIOR CLEANING TO BE UNDERTAKEN USING THE GENULES THANSP DOSSINE. TO ADHERE TO THE SECRETARY OF THE METRIOR'S STANDARDS AND INPS PRESERVATION BRIEF#1: ASSESSING CLEANING AND WATER-REPELLANT TREATMENTS FOR HISTORIC MASONRY BUILDINGS.
 ALL WINDOWS OLDER THAN 25 YEARS MUST BE REMOVED.
 PREPARE EXISTING RAILING TO BE PAINTED.
 CLEAN AND WASH ALL EXISTING WINDOW WELLS. REFER TO NOTE #4;

KEYED DEMOLITION ELEVATION NOTES

- EXISTING BRICK, CONCRETE AND TRIM TO REMAIN, TYP;
- DASSING BRICK, CUNCRELE AND TRIM TO REMAIN, TYP;

 EXISTING BRILDING EXTERIOR ENTRY DOORS TO REMAIN, REPAIR AS NECESSARY, TYP;

 EXISTING BRILDING EXTERIOR ENTRY DOORS TO REMAIN, REPAIR AS NECESSARY, TYP;

 REMOVE ALE DESIGNED EXTERIOR FLACE COURTHENT, TYP;

 REMOVE EXISTING BRILDING OF SAITE TILESISHINGLES AND ASSOCIATED UNDERLAYMENT AND FLASHING WHERE NECESSARY, TYP;

 REMOVE EXISTING GUTTER AND DOWNSPOUT WHERE DAMAGED BEYOND REPAIR, TYP;

 EXISTING EXTERIOR LIGHT FIXTURES TO BE REMOVED, TYP;

 EXISTING EXTERIOR FIXTURES TO REMAIN, TYP;

 EXISTING EXTERIOR TIRM TO REMAIN, TO REMAIN;

 EXISTING SHUTTERS TO REMAIN, REPAIR AS NECESSARY, PREPAIRE TO RECEIVE NEW PAINT, TYP;

 EXISTING SHUTTERS TO REMAIN, REPAIR AS NECESSARY, PREPAIRE TO RECEIVE NEW PAINT, TYP;


 EXISTING SHUTTERS TO REMAIN, REPAIR AS NECESSARY, PREPAIRE TO RECEIVE NEW PAINT, TYP;

(13)	EXISTING RAILING TO BE DEMOLISHED;	
(13)	REMOVE EXISTING WINDOWS:	


DRAWING LEGEND NEW ELEMENT ===== EXISTING ELEMENT TO BE REMOVED BASE BUILDING / EXISTING ELEMENT TO REMAIN



BUILDING 34 - ELEVATIONS A-B BARCROFT PHASE II REHABILITATION



BUILDING 34 - ELEVATION A - DEMOLITION



DRAWING LEGEND

===== EXISTING ELEMENT TO BE REMOVED

BASE BUILDING / EXISTING ELEMENT TO REMAIN

NEW ELEMENT

BUILDING 34 - ELEVATION B - DEMOLITION

GENERAL DEMOLITION ELEVATION NOTES

- REPOINT DETERORIATED MORTAR TO MATCH EXISTING (TYPE, COLOR, COMPOSITION, AND TOOLING) WHERE NECESSARY, REMOVE ABANDONED ITEMS AND SALVAGE REMOVED BRICKS FOR REUSE; REMOVE DAMAGED WINDOW SHUTTERS, TYP: GENITY CLEAN AND WASH ALL DISTING BRICK AND CONCRETE FACADES WITH LOW-TO-MEDIUM PRESSURE. START WITH A VERY LOW PRESSURE (100PSI

- OR BELOW) AND PROGRESS AS NEEDED TO SLIGHTLY HIGHER PRESSURE NOT TO EXCEED 300-400PSL ALL EXTERIOR CLEANING TO BE UNDERTAKEN USING OR BELOW) AND PROCRESS AS NEEDED TO SUGRITY HIGHER PRESSURE NOT TO EXCEED 300-400PS. ALL EXTENDRO CLEANING TO BE UNDERTRIKED THE GENETISE THAN PROSPERIED TO ADHERE TO THE SECRETARY OF THE INTERIOR'S STANDARDS AND INPS PRESERVATION BRIEF#1: ASSESSING CLEANING AND WATER-REPRELANT TREATMENTS FOR HISTORIC MASOMRY BUILDINGS.

 ALL WINDOWS OLDER THAN 25 YEARS MUST BE REMOVED;

 PREPARE EXISTING RAUNG TO BE PAINTED;

 CLEAN AND WASH ALL EXISTING WINDOW WELLS, REFER TO NOTE #4;

KEYED DEMOLITION ELEVATION NOTES

EXISTING BRICK, CONCRETE AND TRIM TO REMAIN, TYP;

EXISTING BRICK, CONCRETE AND TRIM TO REMAIN, TYP;

EXISTING BRUNDING EXTERIOR ENTRY DOORS TO REMAIN, REPAIR AS NECESSARY, TYP;

EXISTING BRUNDING EXTERIOR ENTRY DOORS TO REMAIN, REPAIR AS NECESSARY, TYP;

REMOVE ALE DESIGNED EXTERIOR HAVE COURTHENT, TYP;

REMOVE EXISTING CONTROL OF SAITE IT LESSISSANCES AND ASSOCIATED UNDERLAYMENT AND FLASHING WHERE NECESSARY, TYP;

REMOVE EXISTING GUTTER AND DOWNSPOUT WHERE DAMAGED BEYOND REPAIR, TYP;

EXISTING EXTERIOR LIGHT FIXTURES TO BE REMOVED, TYP;

EXISTING EXTERIOR LIGHT FIXTURES TO BE REMOVED, TYP;

EXISTING EXTERIOR TIME TO REMAIN, PREPAIR TO RECEIVE NEW PAINT;

EXISTING FAILING TO REMAIN, PREPAIR TO RECEIVE NEW PAINT;

EXISTING SHITTERS TO BE DEMAILSHED;

REMOVE EXISTING PRINTS TO BE DEMAILSHED;


REMOVE EXISTING PRINTS WINDOWS;

Bonstra Haresign


.bonstra.com 202 588 9373 T

ARCHITECTS

BARCROFT PHASE II REHABILITATION BUILDING 34 - ELEVATIONS C-D







2 BUILDING 34 - ELEVATION D - DEMOLITION D-DEMOLITION

GENERAL DEMOLITION ELEVATION NOTES

- REPOINT DETERORIATED MORTAR TO MATCH ENSTING (TYPE, COLOR, COMPOSITION, AND TOOLING) WHERE NECESSARY;
 REMOVE ABANDONED TEMS AND SAL VASE REMOVED BRICKS FOR REUSE;
 REMOVE DAMAGED WINDOW SHUTTERS, TYP;
 GENTLY CLEAP AND WORSH ALL EXISTING BRICK AND CONCRETE FACADES WITH LOW-TO-MEDIUM PRESSURE. START WITH A VERY LOW PRESSURE (100PS) OR BELOW) AND PROGRESS AS NEEDED TO SUCHTLY HIGHER PRESSURE NOT TO EXCEED 300-400PSI. ALL EXTERIOR CLEANING TO BE UNDERTAKEN USING THE GENULES THANSP DOSSINE. TO ADHERE TO THE SECRETARY OF THE METRIOR'S STANDARDS AND INPS PRESERVATION BRIEF#1: ASSESSING CLEANING AND WATER-REPELLANT TREATMENTS FOR HISTORIC MASONRY BUILDINGS.
 ALL WINDOWS OLDER THAN 25 YEARS MUST BE REMOVED.
 PREPARE EXISTING RAILING TO BE PAINTED.
 CLEAN AND WASH ALL EXISTING WINDOW WELLS. REFER TO NOTE #4;

KEYED DEMOLITION ELEVATION NOTES

- EXISTING BRICK, CONCRETE AND TRIM TO REMAIN, TYP;
- EXISTING BRICK, CONCRETE AND TRIM TO REMAIN, TYP;

 EXISTING BRUNDING EXTERIOR ENTRY DOORS TO REMAIN, REPAIR AS NECESSARY, TYP;

 EXISTING BRUNDING EXTERIOR ENTRY DOORS TO REMAIN, REPAIR AS NECESSARY, TYP;

 REMOVE ALE DESIGNED EXTERIOR HAVE COURTHENT, TYP;

 REMOVE EXISTING CONTROL OF SAITE IT LESSISSANCES AND ASSOCIATED UNDERLAYMENT AND FLASHING WHERE NECESSARY, TYP;

 REMOVE EXISTING GUTTER AND DOWNSPOUT WHERE DAMAGED BEYOND REPAIR, TYP;

 EXISTING EXTERIOR LIGHT FIXTURES TO BE REMOVED, TYP;

 EXISTING EXTERIOR LIGHT FIXTURES TO BE REMOVED, TYP;

 EXISTING EXTERIOR TIME TO REMAIN, PREPAIR TO RECEIVE NEW PAINT;

 EXISTING FAILING TO REMAIN, PREPAIR TO RECEIVE NEW PAINT;

 EXISTING SHITTERS TO BE DEMAILSHED;

 REMOVE EXISTING PRINTS TO BE DEMAILSHED;

 REMOVE EXISTING PRINTS WINDOWS;

DRAWING LEGEND NEW ELEMENT

===== EXISTING ELEMENT TO BE REMOVED BASE BUILDING / EXISTING ELEMENT TO REMAIN

DRAWING SET NOT FOR CONSTRUCTION

BUILDING 34 - ELEVATIONS -DEMOLITION AD0217

18

Bonstra Haresign

ww.bonstra.com 202 588 9373 T

ARCHITECTS


JAIR LYNCH REAL ESTATE PARTNERS

VIKA VIRGINIA. LLC

SII MAN & 1053 31ST STREET NW WASHINGTON, DC 20007 (202) 336 6230


SUMMIT ENGINEERS

BARCROFT PHASE 2&3 - SECTION ARLINGTON COUNTY, VIRGINIA




NOTE: THIS IS AN ILLUSTRATIVE EXHIBIT PROVIDED TO CONVEY OVERALL INTENT--FINAL LOCATIONS AND QUANTITIES OF IMPROVEMENTS MAY CHANGE AS THE PLAN EVOLVES.

BARCROFT PHASE II REHABILITATION TREE REMOVAL EXHIBIT




EXTERIOR MODIFICATIONS - BUILDING 33

RAMPS AND PATHWAYS SHOWN FOR REFERENCE ONLY, FINAL EXTENT AND LAYOUT TBD



RAILING OPTION #1

ELEVATIONS PROPOSED



GENERAL NEW WORK ELEVATION NOTES

- REPLACE AND/OR INFILL DAMAGED BRICK, CONCRETE, AND TRIM, POINT-UP MORTAR TO MATCH EXISTING;
- GC TO COORDINATE WITH MEP ON ALL NEW HVAC INSTALLATION WORK;
- REMOVE ALL ABANDONED AND NON-OPERABLE EQUIPMENT, DEVICES AND ACCESSORIES;
- REPAINT EXISTING EXTERIOR STEEL PRODUCTS; POWDER COAT, GALVANIZE OR PROVIDE AN EXTERIOR STEEL PAINT THAT CAN ACHIEVE A MINIMUM 10-YEAR MATERIAL WARRANTY;
- BRICK REPAIR FOLLOWING REMOVAL OF PTAC/HVAC UNIT TO MATCH EXISTING SIZE, SHAPE, COLOR AND TEXTURE OF THE ADJACENT BRICK AND MORTAR;
- SEE CIVIL AND LANDSCAPE DRAWINGS FOR NEW SHRUBS AND PLANTS;
- RAILINGS REQUIRED WHERE DIFFERENCE IN ELEVATION IS EQUAL OR GREATER THAN 30";
- HANDRAIL REQUIRED ON RAMPS WITH SLOPE GREATER THAN 5%;
- ACCESSIBLE RAMP NOT TO EXCEED 8% (1:12) SLOPE;

KEYED NEW WORK ELEVATION NOTES

- REPLACE AND/OR PRIME AND PAINT ALL CORRODED METAL LINTELS, OR THOSE NOT ALREADY PAINTED;
- REPLACE IN KIND GUTTERS AND DOWNSPOUTS WHERE DAMAGED BEYOND REPAIR, TYP;
- REPAIR SLATE TILES (MATCH SIZE, SHAPE, COLOR, AND TEXTURE) / ASPHALT ROOF SHINGLES AND ASSOCIATED UNDERLAYMENT WHERE NECESSARY EXISTING WINDOWS TO REMAIN. CLEAN AS NECESSARY TYP:
- REPAIR BUILDING EXTERIOR ENTRY DOORS AS NECESSARY (PAINT, HARDWARE, ETC...), TYP;
- PROVIDE & INSTALL NEW EXTERIOR LIGHT TO MATCH EXISTING (COLONIAL REVIVAL-STYLE LANTERN), TYP;
- NEW INTAKE BRICK VENT PENETRATION:
- NEW BRICK VENT PENETRATIONS (HVAC, BATHROOM EXHAUST), EXACT SIZE AND LOCATION TBD;
- REPAIR AND PAINT EXISTING SHUTTERS AS NECESSARY:
- NEW WINDOW, SIZE AND FINISH (SIMULATED DIVIDED LITE, WHITE VINYL) TO MATCH EXISTING;
- PAINT EXISTING RAILING:


- ADD/ALT: CLAD EXISTING TRIM WITH VINYL OR ALUMINIUM COATED VINYL;
- ADD/ALT: PROVIDE STANDING SEAM METAL CANOPY;
- NEW ACCESSIBLE UNIT ENTRANCE DOOR TO MATCH EXISTING, PROVIDE BRICK ARCHWAYS ABOVE;
- NEW ACCESSIBLE CONCRETE RAMP. SEE CIVIL & LANDSCAPE FOR MORE INFORMATION:
- NEW GALVANIZED STEEL GUARDRAIL AND HANDRAIL TO BE POWDER COATED BLACK;
- NEW CONCRETE LOW WALL;

RAILING OPTION #1



RAILING OPTION #2

ELEVATIONS / PROPOSED



GENERAL NEW WORK ELEVATION NOTES

- REPLACE AND/OR INFILL DAMAGED BRICK, CONCRETE, AND TRIM, POINT-UP MORTAR TO MATCH EXISTING;
- GC TO COORDINATE WITH MEP ON ALL NEW HVAC INSTALLATION WORK;
- REMOVE ALL ABANDONED AND NON-OPERABLE EQUIPMENT, DEVICES AND ACCESSORIES;
- REPAINT EXISTING EXTERIOR STEEL PRODUCTS; POWDER COAT, GALVANIZE OR PROVIDE AN EXTERIOR STEEL PAINT THAT CAN ACHIEVE A MINIMUM 10-YEAR MATERIAL WARRANTY;
- BRICK REPAIR FOLLOWING REMOVAL OF PTAC/HVAC UNIT TO MATCH EXISTING SIZE, SHAPE, COLOR AND TEXTURE OF THE ADJACENT BRICK AND MORTAR;
- SEE CIVIL AND LANDSCAPE DRAWINGS FOR NEW SHRUBS AND PLANTS;
- RAILINGS REQUIRED WHERE DIFFERENCE IN ELEVATION IS EQUAL OR GREATER THAN 30";
- HANDRAIL REQUIRED ON RAMPS WITH SLOPE GREATER THAN 5%;
- ACCESSIBLE RAMP NOT TO EXCEED 8% (1:12) SLOPE;

KEYED NEW WORK ELEVATION NOTES

- REPLACE AND/OR PRIME AND PAINT ALL CORRODED METAL LINTELS, OR THOSE NOT ALREADY PAINTED;
- REPLACE IN KIND GUTTERS AND DOWNSPOUTS WHERE DAMAGED BEYOND REPAIR, TYP;
- REPAIR SLATE TILES (MATCH SIZE, SHAPE, COLOR, AND TEXTURE) / ASPHALT ROOF SHINGLES AND ASSOCIATED UNDERLAYMENT WHERE NECESSARY EXISTING WINDOWS TO REMAIN. CLEAN AS NECESSARY TYP:
- REPAIR BUILDING EXTERIOR ENTRY DOORS AS NECESSARY (PAINT, HARDWARE, ETC...), TYP;
- PROVIDE & INSTALL NEW EXTERIOR LIGHT TO MATCH EXISTING (COLONIAL REVIVAL-STYLE LANTERN), TYP;
- NEW INTAKE BRICK VENT PENETRATION:
- NEW BRICK VENT PENETRATIONS (HVAC, BATHROOM EXHAUST), EXACT SIZE AND LOCATION TBD;
- REPAIR AND PAINT EXISTING SHUTTERS AS NECESSARY:
- NEW WINDOW, SIZE AND FINISH (SIMULATED DIVIDED LITE, WHITE VINYL) TO MATCH EXISTING;
- PAINT EXISTING RAILING:

- ADD/ALT: CLAD EXISTING TRIM WITH VINYL OR ALUMINIUM COATED VINYL;
- ADD/ALT: PROVIDE STANDING SEAM METAL CANOPY;
- NEW ACCESSIBLE UNIT ENTRANCE DOOR TO MATCH EXISTING, PROVIDE BRICK ARCHWAYS ABOVE;
- NEW ACCESSIBLE CONCRETE RAMP. SEE CIVIL & LANDSCAPE FOR MORE INFORMATION:
- NEW GALVANIZED STEEL GUARDRAIL AND HANDRAIL TO BE POWDER COATED BLACK;
- NEW CONCRETE LOW WALL;

RAILING OPTION #2




/ RAILING OPTION #1 - LIGHT MESH SYSTEM

ELEVATION MODIFICATIONS - BUILDING 33

RAILING OPTIONS

RAILING OPTION #2 - CABLE/HORIZONTAL SYSTEM



















EXTERIOR ENTRANCES

BUILDING 30 EXISTING REAR ENTRY DOORS



BUILDING 32 EXISTING REAR ENTRY DOORS



- ARCHED BRICK OPENING/LINTEL

- FIBERGLASS FRAME PER VHDA REQUIREMENTS
- 9 LITE DUAL-PANE INSULATED GLASS
- COLONIAL STYLE
- WHITE COLOR

/ BUILDING 33 PROPOSED ADA REAR ENTRANCE DOORS

- SIMULATED DIVIDED LITE



BASIS OF DESIGN JELD-WEN SMOOTH-PRO 1/2 VIEW BLINDS 9-LIGHT 2-PANEL

BARCROFT PHASE II REHABILITATION WINDOW REPLACEMENTS

WINDOW REPLACEMENTS

EXISTING WINDOWS



EXISTING WINDOW SPECS

MI WINDOW V2000 3500:

- VINYL SINGLE-HUNG
- DUAL-PANE INSULATED GLASS
- COLONIAL STYLE
- WHITE COLOR
- U-VALUE: 0.30
- SHGC: 0.28
- GRID



MATCH EXISTING:

- VINYL SINGLE-HUNG
- DUAL-PANE INSULATED GLASS
- COLONIAL STYLE
- WHITE COLOR
- U-VALUE: 0.30
- SHGC: 0.28
- SDL

/ NEW WINDOWS

FOR REPLACEMENT ONLY



DETAIL OF A SIMULATED DIVIDED LITE (SDL)WINDOW

EXTERIOR LIGHTING FIXTURES

/ EXISTING ENTRANCE



/ EXISTING LIGHT FIXTURE



/ PROPOSED LIGHT FIXTURE

BASIS OF DESIGN: PROGRESS LIGHTING MANSARD TEXTURED BLACK 13" TALL



*NUMBER OF FIXTURES PER BUILDING:

- BUILDING 32: 14

- BUILDING 33: 9

- **BUILDING 34: 5**

BARCROFT PHASE II REHABILITATION FRONT ENTRY - OPTION 1

CANOPY DESIGN - OPTION 1






*NUMBER OF CANOPIES PER BUILDING:

- BUILDING 32: 8
- BUILDING 33: 7
- BUILDING 34: 4








BARCROFT PHASE II REHABILITATION FRONT ENTRY - OPTION 2

CANOPY DESIGN - OPTION 2



/ LINE DRAWING






31

*NUMBER OF CANOPIES PER BUILDING:

- **BUILDING 32: 8**
- BUILDING 33: 7
- BUILDING 34: 4

CANOPY DESIGN - BACK ENTRANCE

/ COLORED ELEVATION



*NUMBER OF CANOPIES PER BUILDING:

- BUILDING 32: 6


- BUILDING 33: 2

- **BUILDING 34: 1**

/ LINE DRAWING



/ SECTION



EXTERIOR FIXTURES TO BE CLADDED WITH VINYL

per VHDA requirements





VHDA REQUIREMENTS

#13- EXTERIOR WOODEN TRIM, BRICKMOLD, SILLS, FASCIA, RAKE BOARDS, AND COLUMNS ARE TO BE CLAD WITH VINYL, VINYL COATED ALUMINUM, OR SIMILAR MATERIALS.

USE MATERIALS DESIGN FOR CLADDING WITH A MINIMUM THICKNESS OF 0.019 INCH AND PROVIDE A STIFFENING CRIMP FOR TRIM AND FASCIA BOARDS THAT ARE MORE THAN 8" WIDE.

REPLACE ALL DAMAGED WOOD PRIOR TO CLADDING. VIRGINIA HOUSING RECOMMENDS THE USE OF COMPOSITE/MANUFACTURED MATERIALS INSTEAD OF WOOD FOR EXTERIOR USE.

EXCEPTIONS MAY BE CONSIDERED FOR HISTORIC BUILDINGS.