


Lubber Run Storm Water Group and Civic Associations

January 13, 2022



Speakers

Aileen Winqvist

Stormwater Communications Manager

703-228-3610

awinqvist@arlingtonva.us

Demetra McBride

Bureau Chief, Office of Sustainability

Environmental Management

703-228-3612

dmcbride@arlingtonva.us

Elizabeth Thurber, P.E.

Stormwater Infrastructure Program Manger

Floodplain Manager

571-289-2498

Ethurber@arlingtonva.us

Lubber Run Storm Water Group					
10-year Capital Improvement Plan Recommendations					
Area of Focus	Issue	Issue Category	Name/Title	CIP Ask	CIP Ask Category
Flooding caused by Virginia Hospital construction	Construction causing more runoff flooding nearby homes	Construction causing flooding	David Easting in ppt	Develop comprehensive water detention, overflow relief plan for Lubber Run watershed. Secured permits on areas affected by Virginia Hospital runoff	overflow relief
			Jim O'Brien/IMA/CA	Request VHC/ Shanda / Arlington County to deliver SWPPP approved engineering plans L&S drawings and any updates with focus on the impact on Lubber Run watershed.	site planning
Flooding from undercapacity storm sewer which that underpounds Lubber Run	Storm sewer is undercapacity and cannot hold street run off during storms	Storm sewer / culvert under capacity	Michael Bruce/WWCA	UES staff proposed a possible simple remedy to Buchanan St flooding - adding a relief pipe between under capacity 15th St catch basin and main N Buchanan St Lubber Run storm pipe. Initiate Site Survey, Site Plan and Site Design to identify cost. Secure funding and contract for this design/build project.	pipes
Site Plans not adding sufficient infrastructure investment	Lubber Run study published 2015 identified undercapacity issue. Commercial development plans have not abated this situation, but have added volume to the system.	Storm sewer / culvert under capacity	Michael Bruce/WWCA	Complete a new storm sewer capacity analysis for the area to include the impact of the new hospital addition to the community.	analysis/study
			Amica Raufala/WWCA	Reach out to residents regarding easement paper to allow the opportunity to identify distributed detention options and complete stormwater infrastructure upgrades.	easements/responsibility
			Amica Raufala/WWCA	Repair failing stormwater outfalls to ensure system integrity and minimize adverse impacts on downstream properties and streams.	overflow relief
TEMA updates to 100-year flood zone for many residents	TEMA trying to push many homes along Lubber Run into a 100-year flood zone, recent County elevation study supported.	Increased flood zoning	David Easting in ppt	Provide further support to homeowners near Lubber Run, submit revised Letter of Map Revision (LOMR) with Arlington analysis results.	update LOMR
Severe erosion along Lubber Run	County is not maintaining it's stormwater channels causing severe erosion and tree loss to	Stormwater causing erosion	David Easting in ppt	Develop a prioritized list of required maintenance	maintenance
			David Easting in ppt	Get public easements clarified	easements/responsibility
Flooding triggered by SR Construction	New large homes are changing the flow of precipitation, causing costly downstream water impact the neighbors. New homes with larger lot coverage pump pump and other flows to stormwater system.	Construction causing flooding	David Easting in ppt	Provide funding support to affected legacy homeowners (homes constructed under legacy zoning rules)	direct homeowner funding
			David Easting in ppt	Add stronger controls and enforcement of stormwater mitigation for new construction	regulation/enforcement
			David Easting in ppt	Lack of clear stormwater drain plan or clarity on responsibility causing water backups	easements/responsibility
			David Easting in ppt	New plans for commercial building should add requirement to fund retention facilities on site	site planning
Maintenance of stormwater drains	Lack of clear stormwater drain plan or clarity on responsibility causing water backups	Inadequate stormwater easements and maintenance	David Easting in ppt	Develop prioritized list of required maintenance and clarify easement responsibility	maintenance
Ballston Beaver Pond - lack of improvements to stormwater detention	Current project does not add additional water detention	Lack of stormwater detention	David Easting in ppt	Perform new elevation, topo, hydro studies of area surrounding Ballston Beaver Pond to determine feasibility of adding additional water detention	analysis/study
Potential stormwater impacts caused by future Loudoun Boulevard redevelopment	Increases to impervious will cause more downstream flooding	Construction causing flooding	David Easting in ppt	Ensure stormwater mitigation measures are required for new development and enforce these	site planning
Under sized culvert at Lubber Run Park & Arlington Boulevard	Under sized culvert causes increased flooding of Lubber Run Park during heavy storms	Storm sewer / culvert under capacity	David Easting in ppt	Work with Virginia to develop a plan to add additional drainage under Arlington Boulevard	pipes
			Eric Arlington Focus	Recommend that Arlington County engage or facilitate a professional hydrology and engineering study to determine appropriate culvert sizes for all of Lubber Run to confirm inadequate sizing of culvert, particularly at Arlington Blvd. This would provide them the necessary data to work with	analysis/study
			Eric Arlington Focus	Recommend that Arlington County Parks remove downed trees from Lubber Run Park that have the potential to float down stream during flooding, further restricting water flow through the culvert under Arlington Blvd.	maintenance
New construction tree removal causes changes in underground water pathways affecting downhill neighbors	More rainfall (climate change) raises water table; construction of larger homes pushes underground water away and on to downhill neighbor; water comes through	Construction causing flooding	Eric/ICA	Annual public assessment of water table levatic restriction of basement sizes requirement that new construction direct water away from adjacent/downhill properties.	new regulations
Over population of deer in Lubber Run Park	Over population of deer depletes the understorey of Lubber Run Park, increasing run off and erosion.	Deer overpopulation exacerbating runoff	Eric/Arlington Focus	The county has recently completed a dose study regarding deer population. Encourage the County to take immediate and appropriate action, including culling deer if warranted.	utility
Lack of funding to commit to Storm Water Management in Arlington	Arlington County appears to lack the resources to adequately address increasing challenges of storm water management. Further, residents and businesses have no incentive to improve storm water management.	Lack of county resources to work issues	Eric/Arlington Focus	Recommend that Arlington County consider establishing a stormwater service fee based on impervious surface on each property. -This would require substantial effort on the part of the county, and may be difficult to implement.	stormwater service feasibility

Agenda – Based on Spreadsheet provided by the Group

Agenda – information requested

VA Hospital

N Buchanan St Flooding

Status of FEMA appeal (for Abingdon Rd. Area)

Erosion in Lubber Run channel and easement clarification

Flooding and Single Family Home Construction

Maintenance of Storm Drainage System

- Easements
- Ballston Pond – additional detention feasibility

Langston Blvd. Planning considerations

Culvert at Lubber Run Park and Rt. 50

Ground water levels and flooding basements

Deer Population in Lubber Run Park

Feasibility of Utility billing based on impervious area

VA Hospital

Hospital is a vital community asset

Hospital installed on site detention (much of site was already impervious – hence they improved the situation)

Hospital agreed to install overland relief channel

Construction issues are being handled by site inspectors

Flooding in watershed appears to be related to system limitations not hospital specifically


Currently working on analysis of entire watershed to determine solutions to flooding (see upcoming slide)

- Detention sites evaluated
- Pipe upgrades evaluated
- Will address updated Capacity Study – Also RAMP
- 10-year design storm for piped system/100-year overland relief path being evaluated

VA Hospital – a few details



Site was already mostly impervious – see air photo



Note Detention, Pipe Upgrades, Overland Flow path

LEGEND:

- CONTRIBUTING DRAINAGE
- URBAN BIORETENTION (ROOFTOP DISCONNECT TO SWM PLANTER)
- CONTRIBUTING DRAINAGE (SHEETFLOW TO URBAN BIORETENTION)
- URBAN BIORETENTION (BIO-TREE PIT)
- PERMEABLE PAVEMENT 1 (POROUS PAVEMENT)
- LIMITS OF SITE WORK
- AREA OF MILL AND OVERLAY (NO LAND DISTURBANCE)

STORMWATER NARRATIVE:
 THE TOTAL SITE AREA IS 5.98 AC. THE LIMITS OF WORK OR LIMITS OF STORMWATER MANAGEMENT IS 7.24 AC. SHOWN AND LABELED. THE EXISTING CONDITIONS ARE 87% IMPERVIOUS, CONSISTING OF THREE 3-STORY OFFICE BUILDINGS AND TWO 1-STORY OFFICE BUILDING AND ASSOCIATED ASPHALT SURFACE PARKING. THE PROPOSED REDEVELOPMENT CONSISTS OF TWO STRUCTURES: A 1-STORY HOSPITAL BUILDING AND A MULTI-STORY PARKING GARAGE STRUCTURE. THE PROPOSED SITE IS APPROXIMATELY 17% IMPERVIOUS AND WILL PROVIDE SWM MEASURES IN ACCORDANCE WITH THE NEW 2014 VIRGINIA STATE REGULATIONS FOR REDEVELOPMENT. THE REQUIRED PHOSPHORUS REMOVAL RATE OF 3.89 POUNDS PER YEAR WILL BE PROVIDED BY THE SWM PRACTICES INTEGRATED INTO THIS DEVELOPMENT.

WATER QUALITY NARRATIVE:
 STORMWATER MANAGEMENT WILL BE PROVIDED USING ON-SITE BMP FACILITIES, CONSISTING OF STORMWATER PLANTERS, BIORETENTION TREE PITS AND PERMEABLE PAVEMENT. THE ROOF AREAS OF THE 3-STORY HOSPITAL BUILDING AND THE PARKING GARAGE STRUCTURE WILL BE REGULATED BY STORMWATER PLANTERS (APPROXIMATELY 13,430 SF OF PLANTER SURFACE AREA TOTAL) LOCATED ON THE BUILDING FOOTING AND ALONG THE STREETSIDES OF BOTH THE GARAGE AND THE BUILDING. PORTIONS OF THE 19TH ST AND EDISON ST WILL SHEETFLOW INTO BIORETENTION TREE PITS. THE BOTTOM OF THE TERRACE PLAZA AND PROPOSED DRIVE ABLE WILL BE TREATED BY LEVEL 1 PERMEABLE PAVEMENT. THE PROPOSED DRIVE ABLE ENTRANCE TO THE GARAGE WILL BE TREATED BY TREE PITS ALONG THE CURB (APPROXIMATELY 3,234 SF OF SURFACE AREA). SEE THIS SHEET FOR PROPOSED LOCATIONS OF BMP FACILITIES AND THE AREAS TREATED.

WATER QUANTITY/RETENTION NARRATIVE:
 AS NOTED ABOVE, THE PROPOSED DEVELOPMENT WILL RESULT IN AN INCREASE OF IMPERVIOUS AREA. THE PROPOSED WATER QUALITY STRUCTURES WILL REDUCE THE RUNOFF FROM THE PROPOSED DEVELOPMENT. ADDITIONAL DETENTION WILL BE PROVIDED FOR THE SUBJECT SITE TO SATISFY THE ENERGY BALANCE EQUATION. (SEE SHEET C-03) FOR CHANNEL PROTECTION AND FLOOD PROTECTION. ADDITIONAL DETENTION FACILITIES IN CONJUNCTION WITH THE RUNOFF REDUCTION PRACTICES LISTED ABOVE, WILL BE DESIGNED TO ENSURE THAT THE TOTAL POST-DEVELOPMENT RUNOFF FOR THE 1 YEAR AND 10 YEAR STORM EVENTS IS EQUAL OR LESS THAN THE EXISTING RUNOFF. THE DESIGN WILL BE COORDINATED WITH ARLINGTON COUNTY DES STAFF, TO ENSURE THAT THE DESIGN DOES NOT RESULT IN AN INCREASE IN FLOOD RISK TO THE DOWNSTREAM PROPERTIES.

OVERLAND RELIEF NARRATIVE:
 THE PROPOSED DEVELOPMENT WILL INCORPORATE AN OVERLAND RELIEF SYSTEM CONSISTING OF A DEDICATED CULVERT TO CONVEY THE ANTICIPATED FLOW FROM THE 100 YEAR STORM EVENT SHOULD THE EXISTING AND PROPOSED STORM DRAIN SYSTEM PIPES AND INLETS BECOME IMPROBABLE TO ENSURE THAT NOF HABITABLE SPACES ARE INUNDAED BY THE 100 YEAR EVENT. THE FINAL DESIGN AND ALIGNMENT MAY BE SUBJECT TO ADJUSTMENTS WITH THE FINAL CIVIL ENGINEERED PLAN. SEE SHEET C-12.

GRAPHIC SCALE:
 1" = 50' FEET
 1" INCH = 50' FT.

VIFA
 ENGINEERS ■ PLANNERS ■ LANDSCAPE ARCHITECTS ■ SURVEYORS ■ GEOMATICS
 VIFA VIRGINIA LLC
 8000 GREENSBORO DRIVE SUITE 200 # TWYNS, VIRGINIA 22093
 (703) 442-7800 ■ FAX (703) 761-2787
 WWW.VIFA.COM

NO.	DATE	DESCRIPTION
NO.1	03/20/18	FINAL 4.1 SUBMISSION
NO.2	04/20/18	SECOND PUBLIC HEARING SUBMISSION
NO.3	05/20/18	PUBLIC HEARING SUBMISSION
NO.4	05/20/18	FINAL 3.1 SITE PLAN SUBMISSION
NO.5	06/20/18	SECOND PUBLIC HEARING 4.1 SUBMISSION
NO.6	06/20/18	FIRST PUBLIC HEARING 4.1 SUBMISSION

COUNTY REVISIONS:

DATE	DESCRIPTION	PROJECT FILE NO.
AUGUST 7, 2017	CONCEIVED	VIRGINIA
DECEMBER 1, 2017		
JUNE 1, 2018		
AUGUST 6, 2018		
SEPTEMBER 13, 2018		

**ARLINGTON COUNTY, VIRGINIA
 DEPARTMENT OF ENVIRONMENTAL SERVICES**

**STORMWATER MANAGEMENT PLAN OVERALL
 VIRGINIA HOSPITAL CENTER
 4.1 SUBMISSION
 Arlington County, Virginia**

SCALE: 1"=50' **SHEET:** C-03



Inundation Zones
FloodFactor.com



Inundation Zones - RAMP

Note: multiple analyses indicate similar inundation zones and flooding areas – FEMA, Floodfactor.com, RAMP and Stormwater Capacity Study

N. Buchanan St. Flooding Solutions

Currently working on analysis of entire watershed to determine solutions to flooding

- Detention sites evaluated
- Pipe upgrades evaluated
- Will address updated Capacity Study – Also RAMP
- 10-year design storm for piped system/100-year overland relief path being evaluated



Status of FEMA Appeals



Appeal submitted on Oct. 18

- Updated community Sept. 13, 2021

Receipt of models and other materials acknowledged by FEMA on Nov. 24, 2021

No additional update from FEMA (except rejection of one resident appeal, dated Dec. 28, which came Jan. 12, 2022)

- No information on their mapping update platform
- Latest communication from FEMA on Jan. 5, 2022 stated that they are working on the review of the appeal and will be communicating 'soon'

Communication expected within 2 weeks) for the schedule for Preliminary Maps is to hold – Preliminary becoming final (FEMA would issue Letter of Final Determination) In **Fall 2022**

Currently working on Updating the County Floodplain Ordinance

Update of County Floodplain Ordinance

Required within 6 months of Letter of Final Determination

New Ordinance must conform to the minimum standards of the NFIP (National Flood Insurance Program)

State of Virginia has developed a model ordinance which meets NFIP minimum requirements, so must conform with that.

Proposed Ordinance must be reviewed and approved by VA DCR and FEMA

Proposed Ordinance must be adopted by County Board

Currently targeting June 2022 for advertising of Ordinance, adoption by Board in July 2022

More information will be forthcoming as we hear from FEMA this month (or not)

If we do not hear from FEMA this month, the schedule may be delayed

Note that it may be easier for FEMA to reject Appeals and issue Letter of Final Determination and hold the existing schedule.

Potential Changes to County Floodplain Ordinance

(per model ordinance)

Note: All items listed are only draft and not final

Regulation of uses within the 0.2% annual probability flood zone (500 year) – restriction on locating specific types of facilities in this flood zone – such restrictions are new to Arlington County

- Restricted uses are emergency services, medical services, government records storage facilities.
- Would require a special exception

Increase residential freeboard from 12 inches to 18 inches for construction of lowest floor elevation (includes basement) above BFE

Increase non-residential freeboard from 12 inches to 18 inches for lowest floor elevation (includes basement) above BFE

- Can floodproof to two feet instead of one foot

Accessory Structures more strictly regulated

Accessory Dwelling units more strictly regulated

Broaden and increase the authority of the Floodplain Administrator


Appurtenant or 'Accessory Structure'

- **Structure Size** - the footprint of the structure can be no greater than 600 square feet in area
- **Characteristics** –
 - Not be used for human habitation
 - Be useable only for parking of vehicles or limited storage
 - Be constructed with flood damage-resistant materials below the base flood elevation
 - Be constructed and placed to offer the minimum resistance to the flow of floodwaters
 - Be anchored to prevent flotation
 - Have electrical service and mechanical equipment elevated to or above the base flood elevation



Accessory Dwelling Unit - 750 sq. ft. or less

- **Structure size** - the footprint can be no bigger than 750 square feet in area.
- **Occupancy** – it can house no more than three people.
- **Characteristics include** – a separate entrance, its own kitchen and bathroom, and must pass a fire-safety regulation inspection.



Flood Insurance Rate Map Update Schedule Reminder

9/18/20: Preliminary maps released

October 2020: County notify property owners

11/18/20: Public meeting


11/19 -12/19/20: 30 day general comment period begins after public meeting – the County submitted comments on several areas, including Abingdon St.

July 2021: 90 day technical appeal period will begin approximately in July 2021. Property owner can submit data to appeal or revise floodplain designation.

Spring 2022 (approx.): FEMA will issue letter of final determination. County will need to update ordinance.

Fall, 2022 (approx.): New FIRMS will be effective

Erosion in Lubber Run Channel



Acknowledgment that erosion is occurring

Current Budget has no funding for any significant channel Maintenance

There are multiple other channels that also need Maintenance. To-date, no prioritization analysis has been completed.

Consideration for new funding will be part of upcoming budget processes (starting Fall 2021)

- Cannot go into details so early in the process
- No decisions on any aspects of CIP have been made yet

EASEMENTS

Still problematic in some locations

No good access to channel

Insufficient width

Flooding Concerns Related to Single Family Home Construction

Help for landowners – currently no program in place

Improve Regulations

- LDA 2.0
- Update IDF curves per RAMP recommendations
- Flood Resilient Design Guidelines Manual – currently under development
- Drainage Maintenance plans and responsibility
 - Clarify responsibility
 - Currently County can only maintain if in public right of way or if in recorded easements
 - County attempts to obtain easements
 - Issues with width required for easements
 - Voluntary acquisition at this time
 - Inlets on private property (even if in public easement) should be kept free and clear of debris by landowners

EASEMENTS

Still problematic in some locations

No good access to channel

Insufficient width

Site Plans for Commercial Properties



Easements


Maintenance – current funding is not adequate

EASEMENTS – see previous slide

Still problematic in some locations




No good access to channel

Insufficient width



Easements

EASEMENTS for Channel



COUNTY OF ARLINGTON, VA. ENGINEERING DEPARTMENT	
LUBBER RUN STORM SEWER EASEMENT FROM CARLYN SPRINGS ROAD TO WILSON BOULEVARD	
SCALE - 1" = 50'	DRAWN BY - <i>SPW</i>
CHECKED BY - <i>SPW</i>	CHECKED BY - <i>SPW</i>
SUBMITTED BY - <i>William D. Dunn</i>	APPROVED BY - <i>William D. Dunn</i>
DATE - 5-18-43	DATE - 5-18-43

Maintenance of Storm Drainage System Ballston Pond and Additional Detention

Maintenance – current funding is not adequate

Ballston Pond – Feasibility of Adding Detention

- Currently does not seem feasible due to constraints with I-66 elevations and need for freeboard
- Potentially could submit LOMR to adjust flows from pond and possibly lower BFE downstream

EASEMENTS – see previous slide

Still problematic in some locations

No good access to channel

Insufficient width

Ballston Pond Project

Construction start –
December 2021

Construction length- 12-
18 months


Reach	River Sta	Profile	Q Total	Min Ch El	W.S. Elev	Crit W.S.	Vel Chnl	Flow Area	Top Width
			(cfs)	(ft)	(ft)	(ft)	(ft/s)	(sq ft)	(ft)
Lubber	2291	1%	1676	236	244.56	241.93	7.14	270.37	150.72

POND ROUTING

	EX PEAK INFLOW [CFS.]	EX PEAK OUTFLOW [CFS.]	EX PEAK ELEVATION [FT.]	PROP PEAK INFLOW [CFS.]	PROP PEAK OUTFLOW [CFS.]	PROP PEAK ELEVATION [FT.]
1-YEAR	238.9	205.2	256.6	238.9	193.1	256.6
2-YEAR	364.8	316.4	257.0	364.8	308.9	257.0
10-YEAR	809.7	703.6	258.1	809.7	703.4	258.1
100-YEAR	1654.7	1146.3	263.0	1654.7	1147.3	263.0

Ballston Pond Design:

1. Improve ecological function
2. Improve water quality function
3. Improve interpretive function
4. Maintains flood attenuation function (actually increases it slightly by approximately 30%)
5. Does not increase base flood elevation
6. Maintains freeboard for I-66



Ballston Pond Design

The original pond was designed to reduce peak flows by 30%, and the new design will maintain that flood mitigation.

The project will remove accumulated sediment from the pond and route water all throughout the pond area in new flow channels, as opposed to flowing directly along one side of the pond as it does now.

There will be regular maintenance after the project is done.

The County has pollution reduction regulations in addition to flood mitigation. This project was designed to maintain the flood mitigation of the pond, and also to add water quality treatment.

Langston Boulevard Planning District

Stormwater modelling was completed to assist this effort

Currently working with the planning team to identify opportunities and areas of need

Some detention opportunities have been identified

Link to the planning effort documents and contacts to planners:

[Plan Langston Boulevard – Official Website of Arlington County Virginia Government \(arlingtonva.us\)](http://arlingtonva.us)

CONTACT US

planlangstonblvd@arlingtonva.us

Coordinator

Natasha Alfonso-Ahmed
703-228-3691

Communications & Engagement

Rachel LaPiana
703-228-0059




Culvert at Lubber Run Park and Rt. 50

Coordinate with VDOT

Study to determine Size – Capacity
Study did not identify any recommended upgrades

Parks to remove debris and downed trees

- Currently Parks does remove debris
- Sometimes our WSS Bureau removes the debris
- Must have public easements to do any work




Capacity Study indicates culvert is surcharged – no recommended upgrades



Instantaneous-data availability statement

Depth to water level, feet below land surface

Most recent instantaneous value: 14.38 01-12-2022 12:15 EST



Add up to 2 mo for "Depth to w below land surf.

2 Add site num

Enter up to 2 sit numbers separatec comma. A site num consists of 8 to digits

GO

Ground water and Basement Flooding

Arlington does not operate any groundwater monitoring wells.

USGS does have groundwater monitoring wells – we sometimes refer to nearby wells for groundwater condition information.

Groundwater levels are typically higher in the winter/spring when plants are dormant, and then go down in late spring/summer as plants are growing/taking up water.

Rainfall amounts can affect groundwater levels.

https://waterdata.usgs.gov/va/nwis/uv/?site_no=385638077220101&PARAMeter_cd=72019,72020

Create [presentation-quality](#) / [stand-alone](#) graph. Subscribe to [WaterAlert](#)

Field Visit data is no longer available on this page, please go to the new Monitoring Location pages to see th

Deer Population in Lubber Run Park

County recently did deer population survey using drones
Arlington has 290 deer at a minimum as surveyed on non-Federal properties.

Four areas of the County showed in excess of 20 animals per square mile, higher than most experts agree is healthy for regeneration of native plants.

Next step is assessment possible management strategies.

DPR is lead agency on this effort.

<https://www.arlingtonva.us/files/sharedassets/public/parks-amp-recreation/documents/arlington-county-deer-survey-and-next-steps.pdf>



Storm Water Utility – billing based on Impervious Area


The County undertook a feasibility study in 2020-2021 to examine the possibility of converting current stormwater fee (based on real estate assessment) to a utility fee (based on impervious cover).

The effort is moving forward with an engagement phase in 2022. An advisory group will be created to provide input and public meetings will be held (likely in summer timeframe).

If approved, the utility would go into effect in FY24.

<https://www.arlingtonva.us/Government/Programs/Sustainability-and-Environment/Stormwater/Stormwater-Utility-Feasibility-Study>

Single Family Detached House



Questions?
