As-Built SWMF Certification for

LDA#

Sheet Index:

Vegetated Roofs #1 and #2:

Certification Letter	2
Checklist	3
As-Built	6
Final Photos	9
Depth measurement	11
Invoice	13
Specification	15
Certification(s)	20
Leak Detection Report	21

Tree Filters #1, #2, and #3:


Certification Letter	23
Checklist	24
Installation/Final Photos, Bio #1	28
Installation/Final Photos, Bio #2	34
Installation/Final Photos, Bio #3	39
Representative Layer Depth Photos	44
Receipts	48
Urban Bio Daily Field Reports	54

Manufactured Treatment Device – Jellyfish

Certification Letter	74
Activation Letter	75

Detention Facility

Certification Letter	77




RE: Stormwater Management System Certification



Dear Sir or Madam:

Stormwater management facilities [2 LEVEL 1 VEGETATED ROOFS] were required as part of the above referenced project date.

Pursuant to 9VAC25-970-55 and Arlington County Code Chapter 60-8, I hereby certify that to the best of my knowledge and belief the stormwater management facilities shown on these record drawings have been constructed in accordance with the approved plans and specifications.



"Certify means to state or declare a professional opinion based on sufficient and appropriate onsite inspections, material tests, as-built survey data, and information provided by other professionals and the contractor, conducted during or after construction."

Enclosures:

- 1. Record Drawings
- 2. Construction Inspection Checklist
- 3. Material Tickets
- 4. Photographs during installation

Construction Inspection Checklist: Green / Vegetated Roof



Address/ Location:		Building Permit #:		VIRGINIA
LDA Permit #:		_ SWM#:		
Contractor: Certifying		Telephone:		
Professional*:		_ Telephone:		
Date Started:	6/22/20	Final Inspection Date:	7/31/20	
		(55) 1 1 1 1 1 1		" • • •

The following checklist provides a basic outline of the anticipated items for the construction inspection of green/ vegetated roofs. An experienced installer should be retained to construct the vegetated roof system. Given the diversity of extensive vegetated roof designs, there is no typical step-by-step construction sequence for proper installation. Inspectors should provide the following information and the timing of inspection verification as needed to document the facility was constructed properly as per the approved plans and VDEQ Design Specification No. 5. The standard for design of this practice is based on the Virginia Stormwater BMP Clearinghouse and the Arlington County Stormwater Guidance Manual.

All items should be checked when completed. Items labeled "Certification of..." must be crossed off, dated and initialed by the certifying inspector.

For items requiring installation by a "certified" installer, corresponding certifications must be attached.

F	PRE-	CONSTRUCTION MEETING	DATE
	\boxtimes	Conduct a pre-construction meeting with the contractor designated to install the green / vegetated roof, the person completing this checklist, and the County DES Stormwater Specialist inspector (schedule via stormwaterreview@arlingtonva.us).	4/1/20

DE	CK CONSTRUCTION	DATE
\boxtimes	Roof constructed with proper slope and material?	4/21/20
	Roof dimensions meet required dimension per approved plans?	
Verify green roof dimensions and surface area (if multiple installations, submit a plat showing locations, and square footage).: GR #1: 1718 sf. GR #2: 1454 sf		4/21/20


V	ATERPROOFING	DATE
D	Waterproofing installed properly per manufacturer's specifications?	4/21/20
Σ	Does waterproofing system require installation by an applicator "certified" by the manufacturer? (If yes, a copy of the certification is required)	6/14/20
Σ	Flood test* performed to ensure system is watertight? (Attach flood test report) *Flood test consists of placing at least 2" of water over the membrane for 48 hours to confirm the integrity of the waterproofing system.	6/14/20

^{*}Certifying professional must be a licensed Professional Engineer (PE), Landscape Architect (LA), or Land Surveyor (LS).


GR	EEN ROOF COMPONENTS	DATE
Verif	y the type of vegetated roof system installed: X Tray System Built In Place System	
X	Do the root barrier, insulation, moisture retention layer, filter fabric and drainage layers meet plan specifications? (Attach invoices and manufacturers certifications)	6/18/20
X	Does the growing media meet plan specifications? (Attach receipts and photos) Verify depth of growing media installed: 4.6"	6/18/20
\boxtimes	Does the metal curbing and flashing meet plan specifications?	6/18/20
	Are all seams, joints and edges caulked and sealed with approved grade of caulk or sealant?	N/A
	Do pedestals, pavers and non-vegetated areas meet plan specifications? Verify location and type:	N/A
PL/	ANTINGS / VEGETATION	DATE
Verif	y the type of vegetated roof system installed: X Tray System Built In Place System	
×	Does the vegetation layer meet plan specifications? (Attach invoices)	
	Verify vegetation source: plugsseeds <u>X</u> pre-grown matspecies mixturecoverage	6/18/20
×	Do the number and type of plants meet the approved planting plan? (Attach photos, if multiple installations submit photo of each location)	6/18/20
COI	MMENTS (CLARIFICATION, DEVIATIONS, ETC.)	DATE
have	ems checked above have been inspected by me (or by an individual under my responsible charbeen completed to my satisfaction and meet the approved plans (or deviations are noted her ature:	
Certi	fying Professional's License Number (or Seal):	

• See attached sealed final location survey with the installed stormwater management facilities appropriately labeled and certification letter

Vegetated Roof As-Built



Vegetated Roof Photos










Vegetated Roof Receipts, Specification, and Other Required Documents



Packing Slip




Ship Date	Ship Via	FOB
6/18/2020		Origin


Item	Description	Shipped	Ordered
	AUSTIN EXPEDITING		
Module CGT4 Deposit	*** P.O. #8003 *** CGT Pre-grown Module (24x24x4) *** P.O. #7736 ***		220 220
	CGT Pre-grown Module (24x24x4)		
Module CGT4 Deposit	*** P.O. #7823 *** CGT Pre-grown Module (24x24x4)		48 48
Module CGT4 Deposit	NORIEGA TRANSPORT *** P.O. #8003 ***		115 115
	CGT Pre-grown Module (24x24x4) *** P.O. #7736 ***		
Module CGT4	CGT Pre-grown Module (24x24x4) *** P.O. #7823 ***		220
Deposit	CGT Pre-grown Module (24x24x4)		220
Module CGT4 Deposit			45 45
Module CGT4			115
Deposit			115

Phone #	Fax #	E-mail









24"



Pre-Grown Tray System


(Patented: 7,603,808)
Product NUMBER: PL4300

Description:

The pre-grown tray provides a turnkey solution that meets or exceeds all guidelines for Green Roofs. The trays are easy to install and feature interlocking edges which prevent shifting or migration of growing media onto the roof membrane. At 24" x 24" x 4.625" deep, the pre-grown tray is appropriate for extensive and semi-intensive vegetative roof profiles. The modules are pre-grown with plants (most commonly sedum) selected by the project designer and shipped to the job site with approximately 90%+vegetation coverage.

Comprised of a heavy duty recycled polypropylene, the Columbia Green Technologies' Tray system is designed with a channelized bottom to maximize stormwater retention. It can reduce both the amount and rate of stormwater run-off and is capable of retaining up to 70% of annual precipitation. Detailed stormwater retention calculations and hydrographs are available upon request.





Planting Options:

• Plants are grown per the project specifications, provided they are appropriate for the local climate zone and sufficient lead time has been provided. Please contact Columbia Green Technologies for more information.

LEED Information:

- Post-Consumer Recycled Content: 88%
- Manufacturing Location: Washougal, WA 98671

Declare Label for Materials Transparency:



The Declare Label is a voluntary disclosure of building material ingredients which offers Living Building Challenge and other project teams concerned about building product ingredients a guide for product specification. We are pleased to announce that our tray system is 'Red List Free' which means it doesn't contain "worst in class" materials, chemicals, and elements known to pose serious risks to human health and the greater ecosystem. www.declareproducts.com

Wind Uplift:

- ANSI/SPRI RP-14 Wind Design Standard for Vegetative Roof Systems is the only Wind Uplift standard for the United States.
- Due to the interlocking design, The Planted-In-Place Tray is considered a #2 Ballast system (Increased wind uplift resistance).
- Please request a copy of the ANSI/SPRI RP-14 User Guide.



System Weight:

Includes 2 lbs/s.f. (cuttings) for plant material weight

System Depth	Dry Weight	Saturated Weight
4.625" Media Depth	15 - 20 lbs./ft ²	25 - 30 lbs./ft ²

^{*} System weights vary by region due to variances in growing media weight contact your local representative for more information.

Packaging/Component Size:

Empty Tray:	
Thickness:	100 MIL.
Dimension:	24"W. x 24"L. X 4.625"
Coverage:	4 ft ²
Weight:	3.6 lbs.
Packaging:	Stacked – 400 trays/pallet
Pre-Vegetated Tray:	
Typical Weight for Handling	+/- 100 lbs. each
Purposes Only:	

Installation:

- 1. Prior to installation, it is the Project Representative's responsibility to consult with a registered structural engineer to determine whether the structure is adequately reinforced to withstand the weight of a fully saturated vegetative tray.
- Perform tray installation only after a representative from the roofing membrane manufacturer has inspected the membrane and found it to be in accordance with the membrane manufacture's Specifications.
- Place the vegetative trays directly on the roofing membrane or protective layer as determined by the membrane manufacture.
- 4. Using the interlocking sides, overlap the vegetative trays.
- 5. After all trays have been installed, irrigate plant material to ensure growth.

Storage:

- Upon delivery, move plants out of direct sun to a cool location and remove cellophane wrapping.
- Trays may be left unstacked for a maximum of 12-hours, provided they are kept in the shade.
- Water 2-3 times per week until the trays are installed on the roof.
- Store away from sources of ignition and extremely high temperatures.

Precautions:

- Confirm with a certified Structural Engineer that the structure can support the saturated weight of the vegetative roof system.
- To facilitate drainage a minimum roof slope of 1/8" in 12" min. must be provided.
- System components should not be installed when the weather is below 45 °F (7.2 °C) or above 95 °F (35 °C).
- Do not drag modules into position.
- · Use caution when lifting trays.
- Check roof drains regularly to ensure there are no obstructions to impede water flow.
- · Wash exposed skin prior to eating, drinking or smoking and at the end of each shift.
- Wear impermeable protective clothing, eye wear and self-contained breathing apparatus when cutting trays.



Pre-Grown Tray Plant Mix:

The sedums in this mix are selected for hardiness and grown outdoors so that they are acclimated and have a proven ability to survive wind, cold, heat, drought, and tough environments that limit plant choices. Each pregrown tray contains the following species:

Plant Name	Deciduous / Evergreen	Flower Color	Winter Interest	Zone	Soil Depth	Mature Height	Width
Sedum spurium 'Fuldaglut'	Deciduous	Red	Yes	5-10	3-4"	4-6"	6-8"
Sedum spurium 'John Creech'	Deciduous	Pink	Yes	3-10	3-4"	4-6"	6-8"
Sedum spurium 'Red Carpet'	Deciduous	Red	Yes	3-7	3-4"	3-4"	8-10"
Sedum kamtschaticum	Deciduous	Yellow	Yes	4-7	3-4"	5-6"	6-8"
Sedum kamtsch. 'Variegatum'	Deciduous	Yellow-Red	No	4-10	3-4"	8"	12"
Sedum takesimensis 'Golden Carpet'	Deciduous	Yellow	Yes	4-8	3-4"	4-6"	8-10"
Sedum acre 'Aureum'	Evergreen	Yellow	Yes	4-7	3-4"	1-2"	12-15"
Sedum acre 'Gold Moss'	Evergreen	Yellow	Yes	4-7	3-4"	1-2"	12-15"
Sedum album 'Coral Carpet'	Evergreen	White	Yes	4-8	3-4"	0.5-1"	6-8"
Sedum album 'Murale'	Evergreen	Light Pink	Yes	4-8	3-4"	2-4"	12-18"
Sedum stefco	Evergreen	White	Yes	5-8	3-4"	1-2"	6-8"
Sedum floriferum 'Weihenstephaner Gold'	Evergreen	Gold	Yes	3-10	3-4"	6"	8-12"
Sedum reflexum 'Blue Spruce'	Evergreen	Yellow	Yes	5-10	3-4"	12"	6-8"
Sedum rupestre 'Angelina'	Evergreen	Yellow	Yes	4-10	3-4"	5"	6-8"
Sedum sexangulare	Evergreen	Yellow	Yes	4-10	3-4"	3-4"	6-8"
Sedum x Immergrunchen	Evergreen	Yellow	Yes	4-7	3-4"	5-6"	6-8"



Extensive Growing Media

Product NUMBER: GM3000-EXT

Description:

The following technical information sheet covers the production and materials for use in lightweight growing media blends on extensive vegetative roof assemblies.

Our extensive vegetative roof growing media is regionally blended and formulated to meet the rigorous standards of the FLL Guidelines for particle size gradation, fines content, dry and saturated bulk density, total porosity, air filled porosity, water retention, hydraulic conductivity, pH balance, soluble salt content and organic matter content.

The growing media is created using only high quality and local sourced product to the greatest extent possible. Per FLL Guidelines this growing media is derived from industry proven materials consisting inorganic and organic materials.



Physical Characteristics:

- 1. Expanded Media Component:
 - a. Description: Inorganic expanded Media that is consistent with Pumice, Perlite, Volcanic Cinder Rock, or lightweight expanded clay aggregate.
- 2. Compost Component:
 - a. Description: Nutrient grade compost that is manufactured from recycled material and is mixed with the other three components by a composter that is enrolled in the United States Compost Council's (USCC) Seal of Testing Assurance (STA) Program.
 - Only compost products the meet all applicable state and federal regulations,
 Section 07 33 63 www.federalgreenspec.wbdg.org pertaining to its production and distribution are used in this application.
 - c. All approved compost products meet all applicable state and federal regulations for chemical contaminants (e.g. heavy metals, pesticides, etc.) and pathogen limits pertaining to the source materials in which it was derived.
- 3. Organic Component:
 - a. Description: Fiber or organic material that is a clean cellulose product that adds friability to media, filtration, and agronomic horticultural attributes.

Storage:

- Store in a dry area free of potential contaminants which may adversely affect the engineered blend including potential weed seeds.
- Store away from sources of ignition and extremely high temperatures, when media is shipped in bags or totes.

Precautions:

- When media is placed in bags or totes, avoid prolonged exposure to sunlight, heat, sparks and open flames.
- When media is delivered in bulk, cover media piles as needed to reduce effects of potential weather conditions including heavy rains and winds.
- Wash exposed skin prior to eating, drinking or smoking and at the end of each shift.

LEED Information:

Manufacturing Location and Post-Consumer Recycled Content:

• Varies; contact Columbia Green for project-specific information.



Physical Properties*:

Proportion of silting components < 0.063 mm	Mass %	<u><</u> 15
		_
Proportion of particles < 0.25 mm 60 mesh	Mass %	5 - 30
Proportion of particles < 1.00 mm 18 mesh	Mass %	10 - 50
Proportion of particles < 2.00 mm 10 mesh	Mass %	30 - 70
Proportion of particles < 3.20 mm 1/8 inch	Mass %	40 - 80
Proportion of particles < 6.30 mm 1/4 inch	Mass %	65 - 95
Proportion of particles < 9.50 mm 3/8 inch	Mass %	100
Density Measurements		
Bulk Density (dry weight basis)	lb/ft ³	44 - 53
Bulk Density (at max. water-holding capacity)	lb/ft ³	72 – 85
Water/Air Measurements		
Total Pore Volume	Vol. %	<u>≥</u> 50
Maximum water-holding capacity	Vol. %	35 – 65
Air-filled porosity at max water-holding capacity	Vol. %	<u>≥</u> 10
Water permeability (saturated hydraulic conductivity)	in/min	0.024 – 2.83
pH and Salt Content		
pH (in CaCl ₂)		6.0 - 8.0
Soluble salts (water, 1:10, m:v)	g (KCI)/L	< 3.5
Organic Measurements		
Organic matter content	g/L	25 - 65
Nutrients		
Phosphorus, P205 (CAL)	mg/L	≤ 200
Potassium, K2O (CAL)	mg/L	≤700
Magnesium, Mg (CaCl2)	mg/L	<u>−</u> ≤ 200
· · · · · · · · · · · · · · · · · · ·	- 101 -	

^{*} Volume measures are guaranteed at the time of production and packing. Settling of materials may occur during transportation and handling. Minor deviations from test data may occur due to the natural variability of the bulk materials used to produce the media blend

Packaging/Component Size:

Туре	Volume	Approx. Delivery Weight
1.5 cf. Bags	1.5 cf bags. (palletized in 1 cy increments)	1,250 lbs.
1.5 cy Tote	1.5 cy	1,850 lbs.
2.0 cy Tote	2.0 cy	2,500 lbs.
Bulk	40-60 cy. / truck (weight dependent)	48,000 lbs. (more with tandem)

^{*} Recommended 10%-15% additional growing media (by volume) be ordered to account for long term settling of product.



CERTIFIED INSTALLER of GREEN ROOFING



This installer has received advanced training in the best practices of Green Roofing and is hereby recognized as a Certified Installer of the comprehensive green roof solutions provided by Columbia Green Technologies.



Ref: Electronic Leak Detection (ELD)

ASTM-D 7877 Compliant -


Electronic Leak Detection


With innovative leak detection equipment, electricity can now be utilized to follow the path of a leak; allowing its exact pinpoint location without the application of hundreds or thousands of gallons of water used in traditional flood testing.



The power source is grounded to the conductive structural deck. When the electronically charged piece of equipment locates a breach in the membrane (insulator) the circuit is completed emitting an audio tone to the technician. When the unit locates a breach within the tested area, the operator will then sweep that area again, however this time the contact area is reduced to pinpoint the exact location.

No water needs to be used in this method of testing. The membrane must be dry. This testing will locate the precise locations of breaches.






RE: Stormwater Management System Certification



Dear Sir or Madam:

Stormwater management facilities [3 LEVEL 1 URBAN BIORETENTION TREE FILTERS] were required as part of the above referenced project date.

Pursuant to 9VAC25-970-55 and Arlington County Code Chapter 60-8, I hereby certify that to the best of my knowledge and belief the stormwater management facilities shown on these record drawings have been constructed in accordance with the approved plans and specifications.



"Certify means to state or declare a professional opinion based on sufficient and appropriate onsite inspections, material tests, as-built survey data, and information provided by other professionals and the contractor, conducted during or after construction."

Enclosures:

- 1. Record Drawings
- 2. Construction Inspection Checklist
- 3. Material Tickets
- 4. Photographs during installation

Construction Inspection Checklist: Urban Bioretention –Tree Filter



Address/ Location:		Building Permit #:	B A R	VIRGINIA
LDA Permit #:	LDA	SWM#:	SIUM #	9 (0)
Contractor: _ Certifying		Telephone:		
Professional*:		Telephone:		
Date Started:	5 24 2021	Final Inspection Date:	8/16/2021	

The following checklist provides a basic outline of the anticipated items for the construction inspection of urban bioretention facilities. This checklist does not necessarily distinguish between all the design variations. Inspectors should review the plans carefully, and adjust these items and the timing of inspection verification as needed to ensure the intent of the design is met. The standard for design of this practice is based on Virginia Stormwater BMP Clearinghouse and Arlington County Stormwater Guidance Manual.

All items should be crossed off when completed. Items labeled "Certification of..." must be crossed off, dated and initialed by the certifying inspector.

PRE	RE-CONSTRUCTION MEETING	
v	Conduct a pre-construction meeting with the contractor designated to install the tree filter, the person completing this checklist, the County urban forester, and the County DES Stormwater Specialist inspector (schedule via stormwaterreview@arlingtonva.us).	2/11/2

EXC	AVATION AND FILTER CONSTRUCTION	DATE
ď	Area is marked and the size and location conforms to plan.	5/24/21
ত	Excavation has achieved proper grades and the required geometry and elevations.	5/26/21
Q'	Filter is constructed using the material specified and to the required dimensions as shown on the approved plans.	6/4/21
I	Impermeable Liner and/or waterproofing,if specified.	5 27 21
র্ভ	Certification of Excavation and Filter Construction Inspection: Inspector certifies the successful completion of the steps listed above, has surveyed the dimensions and the following items are attached. As-built elevations required: Bottom of the cell; Curb Cut - top of curb; Curb Cut - bottom of curb; Curb Cut - depressed inflow. Photos required include: Excavated Depth	5 27 21

FIL	TER LAYER, UNDERDRAIN, AND STONE RESERVOIR PLACEMENT	DATE
V	All aggregates conform to specifications as certified by quarry.	5/27/21
V	Underdrain size and perforations meet the specifications. Placement of underdrain, observation wells, and underdrain fittings are in accordance with the approved plans.	5/27/21

^{*}Certifying professional must be a licensed Professional Engineer (PE), Landscape Architect (LA), or Land Surveyor (LS).

V	Elevations of underdrain and outlet structure are in accordance with approved plans.	5 27 21
4	Placement of remaining lift of stone reservoir layer as needed to achieve the required reservoir depth.	5/27/21
	Certification of Filter Layer and Underdrain Placement Inspection: Inspector certifies the successful completion of the filter layer and underdrain placement steps listed above. Photos, elevations, and material delivery tickets for these items are attached.	
র্ত্ত	Photos required include: Perforated underdrain pipe with a solid vertical overflow pipe; Depth of #57 stone; Depth of choker stone (pea gravel or #8). As-built elevations required: Underdrain invert; Top of #57 stone; Top of choker stone. Material delivery tickets required: #57 stone and choker stone (pea gravel or #8)	5 27 21

CONNECTION TO STORM SEWER		DATE
র্	Underdrain is tied into the public storm sewer system and the connection has been witnessed by County inspector (if applicable).	5/27/21
v'	Certification of Connection to Storm Sewer: Inspector certifies the successful completion of connection to the storm sewer. As-built elevation required for each connection.	5 27 21

BIO	RETENTION SOIL MEDIA PLACEMENT	DATE
₫	Soil media is certified by supplier or contractor as meeting the project specifications and comes from an approved soil media vendor.	5 28 21
Ø	Soil media is placed in 8-12 inch lifts with no machinery allowed directly on the media during or after construction. The media should be overfilled above the proposed surface elevation, as needed, to allow for natural settling. Lifts may be lightly watered to encourage settling. After the final lift is place, the media should be raked (to level it), saturated and allowed to settle for at least one week prior to installation of plant materials. No filter fabric is to be used between the stone layer and the soil layer.	5 28 21-
☑ [′]	Certification of Soil Media Placement Inspection: Inspector certifies the successful completion of the soil media steps listed above. Elevation has been verified after settlement. Photos of installation, elevation of top soil media, and material delivery tickets for the soil media are attached.	6 4 21

PRE	TREATMENT AND PLANT INSTALLATION	DATE
☑	Placement of energy dissipaters and pretreatment practices (splash block/rocks, gutter guards, etc.) are installed in accordance with the approved plans.	8/16/21
Ø	Overflow has atrium or beehive grate installed.	6/4/21
V	Inflows are installed in accordance with the approved plans providing the correct drainage area. Including the placement of energy dissipaters and pretreatment practices (splash block/rocks, gutter guards, etc.) are installed in accordance with the approved plans.	8/16/21
☑ ′	The number and spacing of plants are installed in accordance with the approved plans.	8/16/21
Ø	A 2-3 inch layer of shredded hardwood mulch has been installed.	8/16/21
	Certification of Pretreatment and Plant Installation Inspection: Inspector certifies the successful completion of the pretreatment, energy dissipaters, plants, overflow grates and mulch as listed above. Photos, elevations, and copies of material delivery tickets are attached.	3 16 21
	Photos required for this step for each planter include:	

- Overall photo showing the number of plants installed;
- Location of curb cut with the appropriate splash block/rocks.

As-built elevations required:

- Riser; and
- Top of mulch.

Material delivery tickets required for this step include:

- Approved plants listing number and species;
- Shredded hardwood mulch.

DATE

All items checked above have been inspected by me (or by an individual under my responsible charge) and have been completed to my satisfaction and meet the approved plans (or deviations are noted here).

Signature: ______ Date: ______ Date: ______


Certifying Professional's License Number (or Seal): License #

See attached plat and as-built with the following information:

- Interior dimensions of cell
- Elevations
 - Cell bottom;
 - Underdrain invert;
 - Invert to storm sewer;
 - Top of #57 stone;
 - Top of choker stone;
 - Top soil media;
 - Riser;
 - Top of mulch;
 - Curb Cut top of curb;
 - Curb Cut bottom of curb;
 - Curb Cut depressed inflow.



Required Urban Bioretention Tree Filter #1 Photos



Tree Filter #1: Excavation and installation of impermeable liner




Tree Filter #1: Installation of perforated underdrain pipe and solid vertical overflow pipe



Tree Filter #1: Curb Cut inflow with splash rocks installed




Tree Filter #1: Top of mulch to crest of overflow pipe, Ponding Depth = 4"



Tree Filter #1: Overall completed tree filter facility with plants, mulch, and splash rocks installed.


Required Urban Bioretention Tree Filter #2 Photos




Tree Filter #2: Installation impermeable liner, perforated underdrain pipe, and solid vertical overflow pipe



Tree Filter #2: Curb Cut inflow with splash rocks installed



Tree Filter #2: Top of mulch to crest of overflow pipe, Ponding Depth = 4"



Tree Filter #2: Overall completed tree filter facility with plants, mulch, and splash rocks installed.

Required Urban Bioretention Tree Filter #3 Photos




Tree Filter #3: Installation impermeable liner, perforated underdrain pipe, and solid vertical overflow pipe



Tree Filter #3: Curb Cut inflow with splash rocks installed



Tree Filter #3: Top of mulch to crest of overflow pipe, Ponding Depth = 5"



Tree Filter #3: Overall completed tree filter facility with plants, mulch, and splash rocks installed.

Representative* Urban Bioretention Tree Filter Layer Depth Photos

*Representative Photos are provided here of each Tree Filter layer to show that Tree Filter layer depths are in general at the required depths per the approved plans. Tree Filter As-Built elevations of top of each layer are provided on Sheet C-in the CEP As-Built Plan.



Representative #57 stone depth = 9"



Representative #8 stone depth = 3"



Representative bioretention soil filter media depth = 48"

Urban Bioretention Tree Filter Receipts



INVOICE



To ensure proper credit, please include remittance or list invoice numbers on your check remittance and send to:

Vulcan Construction Materials,LLC PO Box 75219 Charlotte, NC 28275-5219, US

Phone: 1-800-777-8752 or help@vmcmail.com

CUSTOMER NO:

INVOICE NO:

INVOICE DATE: 03/10/2021

INVOICE AMT:

ORDER:

DUE DATE: 04/15/2021


Invoices not Finance including but rendered	paid accord Charge. Cu t not limited t by suit or otl	ing to our cr ustomer shat to a reasona herwise in o	credit terms will all pay all cost of able attorney's collecting past o	be assesse of collection fee for serv due invoices	ed a vices s.					SAL	ES TAX:		TOTAL PI	RODUCT:			Pay this	AMOUNT:
TOTAL QUA	NTITY:		TOTAL LO		3.00					1 22	.3.		TOTAL O	THER:			_	
	SALE	ES REP			PO NUM	IBER	F	REF		co	NTRACT NO.			TAX EXE	MPT ID.			ERMS
INVOICE	# INVC	DICE DATE	CUSTOMER	NUMBER	LOCATION		LOCATION	ORDER			BILL OF L	ADING			FOE	3	full by he month folio	ROX - Payable in a 15th of each owing month of ipment
		/10/2021									5,22 5, 2				DELIV		-	pment
				TICI	KET DETAIL					PRODUC	СТ		FREIGHT			ADDED CH	IARGES	AMOUNT
SHIP DATE	TICKET	VEHIC	LE	CLASS		D CODE	DESCRIPTIO	ON	UOM	QTY	PRICE	UOM	QTY	PRICE	UOM	QTY	PRICE	AMOUNT
03/08/2021			STAN	IDARD	25240	Dou	uble Washed VA #57					▮▮						
			STAN	IDARD	25240	Dou	uble Washed VA #57											
			STAN	IDARD	28170	Dou	uble Washed VA #8							-				
Rece	ive your in	voice faste	er and help sa	ave the en	vironment t	SAVE by enrolling in	TIME AND SAVE A T n our email invoicing s help@vmcmail.co	REE WITH EMA	AIL IN	VOICE DE	LIVERY! sent in one	easy t	o open file di	irectly to y	our Ir	nbox. To s	sign up, cont	act us at

LUCK	X MS.	Ecosystems - 27672 Gum S Chantilly VA	Spring Road		Tel:(703) 830-888 Fax:(703) 754-82		
		Date/Time:	03/09/2021 06:28	Ref #:		Ticket #:	
		Cust #:		Order:		P.O. #:	
		Quotation:				_	
Max Gross: 75075 lbs	Scale Wt: 74800 lbs	4 Tare Wt: 27820 lbs	Net Wt: 46980 lbs	 Net Tons: 23.49 Shrt	Material Rate: \$32.50 T	Material Haul FSC	
Truck#:	Hauler#:	Hauler Name:		21.31 Mtr	Haul Rate:	Total Charges:	
59963p-59963	002040	WeighMaster			\$9.50 T	Sales Tax:	
Ordered: Visit https://www		om/sites/default/fil		21.31 Metric	1 Load(s)	Received By: X customer	<u>View</u> <u>Map</u>

QUAIL RIDGE PRODUCTS 4821 Massaponax Church Rd Fredericksburg, VA, 22407

PHONE: (540) 898-7434





Received By



5870 Leedstown Rd. Oak Grove, VA 22443 Phone: (804) 224-7111 Fax: (888) 236-3104 **Shipping Ticket**

INVOICE NO. CUSTOMER NO.

NOTE 1:

BM 6)

Bill To:

ShipTo:

11.000 101 w

FOR PICK UP WEEK OF	SHIP VIA	F.O.B		TERMS	
	Trailer			Net 60	
PURCHASE ORDER NUMBER	ORDER DATE	SAL	ES PERSON		

PURCHASE ORDER N	UMBER ORDER DATE	SALES PERSON
QUANTITY ORD SHIP	DESCRIPTION	
Ø 96. 96	Andropogon gerardii 'Red October' #	#3 Per
• 0	–Cornus florida 'Cloud-Nine' 2.5 - 3" E ≺ING 55-59 A	Ē&Β
18, 18	Fothergilla gardenii 18 - 24" #3 Cont 185	t
32	_ttea-virginica.'Little-Henry'-PP-10988- 181	-1518"#3 ⁻ Cont
\$ 397 · 397	Panicum virgatum 'Shenandoah' #3 I 309, SHIP A	Per
\$ 6 " (2	Prunus yedoensis 3 - 3.5" B&B	

Itea virginica 'Little Henry' PP10988 15 - 18" #3 Cont new crop avail in spring 20



BILL TO:

Manor View Farm

Wholesale Nursery, Growers Distributers 15601 Manor Road

Monkton MD 21111

Phone: (410) 771-4700 Fax: (410) 771-8246

sales@manorview.com

ACKNOWLEDGEMENT

ORDER

DATE

PAGE

6/29/2021

Page 1 of 1

SHIP TO:



SHIP DAT	Έ	SHIP VIA	Customer#	Customer #			TERMS			
05/13/202	21				C.O.D.					
PO NUMBI	ER	ORDER DATE	SALESP	ERSON						
		04/22/2021								
PRODUCT ID	QTY	DESCRI	PTION	SIZE	UNIT PR	RICE	DISC%	NET PRICE	EXT. PRICE	
	3	AMEL. X GRAND. 'AUTU		10 FT						
	2	AUTUMN BRILLIANCE SERVICEBERRY NYSSA SYL. 'WILDFIRE' WILDFIRE BLACK GUM			1					
	28	PRUNUS LAUR. 'SCHIPKAENSIS' *net price SKIP LAUREL		#6						
	3	RHOD. CAT. ALBUM WHITE RHODODENDRON		#7						
	4	ROSA X DOUBLE KNOC REBLOOMING DOUBLE ROSE		#3						

Signature_____ Date ____

Unless Otherwise Noted Under Terms,

TERMS AND CONDITIONS OF PAYMENT: Terms are C.O.D. from invoice date

A finance charge of 1.5% will be charged monthly on all past due invoices. In the event it becomes necessary for Manor View Farm, Inc. to file suit to enforce payment of past due amounts Manor View Farm, Inc. shall be entitled to collection fees, court cost and interest at 18% annum.

Subtotal:
Sales Tax:
Discount:
Additional Charges:
Freight:
Amount Due:

Daily Field Reports

			ı	Day & Date:	
Project:				Project#:	
Location:			25100.00	resentative:	
Client Name:			Te	emp Range:	
Contractor:				Weather:	
Description of Work:			Location:		
Bioretention Construction	ſ		Bioretention # 1	8	
Building Permit Number	В				
Tests Performed: Biore	tention Construct	ion: Visual Observation	`%'		
Problems/Non-Complian	es/Failing Tests:	Yes □ No ⊠	(if yes, detail v	vithin Inspection Findings I	below)
		INSPECTION F	INDINGS:		1,5-20
<u> </u>					
impermeable liner and t specifications. The professional engineer opinions to the client. The contractual requirements. have performed our servi- expressed or implied, as to	is represented on sepresence and act. The contractor reces in accordance the professional sepresence of a place.	depth of VDOT #57 stor VDOT #57 observed tod site solely to observe operativities of the engineer's rations sole responsibility for with generally accepted gervices provided.	nes under the 6" lay appeared to b ations of the contro representative do n or site safety and the geotechnical engine	rmeable liner at both sides SCH.40 PVC perforated poer in accordance with the actor identified, form opinion of relieve the contractor's the methods and sequence eering practices. We make	pipe. The laying of e project plans and ons and report those s obligation to meet of construction. We no warranty; either
revision by our managers acceptance can only be	and engineers. T	he statements made her	rein do not constit	d representative and is su tute a certification. Appro- d on this data are the resp	val of work for final
Time of Arrival	8:15 AM 11:15 AM 03:30 PM	Time of Departure:	09:45 AM 01:45 PM 04:00 PM	Total Time Onsite:	4.5
80		\$%	¥3	Lab Time:	
<u>v</u>			_	Other ():	
Trip Charge:*		Mileage:*		Travel Time*:	2.00
*will be billed	in accordance	with contract		Total Time:	6.50



Project: Location: Client Name: Contractor:



Day & Date: Project#: Representative: Temp Range: Weather:






Bioretention #1 excavated up to the designated elevation



Project: Location: Client Name: Contractor:







Impermeable liner and underdrain installation



Project: Location: Client Name: Contractor:









#57 stone installation, 9"

Project: Location: Client Name: Contractor: Description of Work: Bioretention Construction Building Permit Number: B:		Rep	Day & Date: Project#: resentative: emp Range: Weather:	
NAME OF THE PARTY	ction: Visual Observation) 10/1902 to 2000000.00000	90707 820 000 PROLE DO	14539 PROPE
Problems/Non-Compliances/Failing Tests			within Inspection Findings	below)
	INSPECTION F	INDINGS:		39
representative the rest of #57 stones up to 13" and plac two 6" cleanout pipes of the bioretentior today appeared to be in accordance with The professional engineer is represented or opinions to the client. The presence and a contractual requirements. The contractor of have performed our services in accordance expressed or implied, as to the professional This report is the instrument of service of a professional engineer involved. Please see the attached pictures of work in	were installed. The place the project plans and spec site solely to observe oper- ctivities of the engineer's retains sole responsibility for with generally accepted g services provided.	nes then 4 ft of the ment of VDOT #5 difications. ations of the contractions representative do for site safety and the geotechnical engin	ne bio media at the bioret 7, choker stones and the actor identified, form opini not relieve the contractor' he methods and sequence eering practices. We make	ention #1. Also, the bio media observed ons and report those is obligation to meet of construction. We no warranty; either
This report constitutes a summary of or revision by our managers and engineers. acceptance can only be made by our ma	The statements made her nagers and engineers. Into	ein do not constit erpretations base	tute a certification. Appro d on this data are the resp	oval of work for final consibility of others.
Time of Arrival: 9:45 AM	Time of Departure:	04:15 PM	Total Time Onsite:	6.5
		_	Lab Time: Other ():	
Trip Charge:*	Mileage:*		Travel Time*:	2.00
*will be billed in accordance	with contract		Total Time:	8.50



Project: Location: Client Name: Contractor:









Placement the rest of #57 stones and the two cleanout pipes installed



Project: Location: Client Name: Contractor:







#8 stone installed, 3"



Project: Location: Client Name: Contractor:










First 2 feet of soil media installed




Project: Location: Client Name: Contractor:







Total of 4 feet of soil media installed



Other ():

2.00

11.50

Travel Time*:

Total Time:

Project: Location: Client Name: Contractor:		Repr	Project#: esentative: emp Range: Weather:	
Description of Work:		Location:		
Building Permit Number: B & B:		Urban bioretention	on #2	
Tests Performed: Bioretention Construc	ction: Visual Observation			
Problems/Non-Compliances/Failing Tests	Evaporation (Co.)	140000000000000000000000000000000000000	ithin Inspection Findings	below)
	INSPECTION F	INDINGS:		
the pond were 12' x 6' x 6'. The pond ext of VDOT #57 stones and laid the 6-inch p giving a total of about 18-inches of VDO backfilled the non-perforated 6-inch PVC. The professional engineer is represented those opinions to the client. The presence to meet contractual requirements. The construction. We have performed our ser no warranty; either expressed or implied, This report is the instrument of service of the professional engineer involved.	erforated PVC pipe. About DT #57 stones. No choker pipe connection bioretent on site solely to observe or e and activities of the engine contractor retains sole re- vices in accordance with go as to the professional services	to Station 10 + 88. 12-inches of VDO stones were plaction #1 and biorete perations of the coneer's representat sponsibility for site enerally accepted givices provided.	The contractor placed at T #57 stones was further during this working ntion #2. Intractor identified, form ive do not relieve the contractor identified at the methor geotechnical engineering	about a 6-inch depth r placed on the pipe day. The contractor opinions and report ntractor's obligation ds and sequence of practices. We make
This report constitutes a summary of or revision by our managers and engineers. acceptance can only be made by our ma	The statements made her	ein do not constitu	ute a certification. Appro	oval of work for final
Time of Arrival: 7:30 AM	Time of Departure:	5:00 PM	Total Time Onsite:	9.50
			Lab Time:	

Mileage:*

Trip Charge:*

*will be billed in accordance with contract



Photo 1: Bioretention # 2 Excavation process



Photo 2: Bioretention # 2 Impermeable liner material laid on sides of the facility

Project Name:	SWM ID: 2				
	Date:				
Project No.:	Prepared By				
	Scale: As Shown ☐ Not to Scale ☑				





#57 stone installation

Project Name:

Date:

Project No.:


Prepared By:

Scale: As Shown □ Not to Scale ☒



#57 stone installation, 9"

	Project Name: Project No.	SWM ID: 2
		Date:
		Prepared By
		Scale: As Shown ☐ Not to Scale ☑



Project:					Day & Date: Project#:	
Location:				Ren	presentative:	
Client Name:				1		
Contractor:						
			2			
Description of W				Location:	TO MICHIES	
Bioretention Cons	truction			Urban bioreten	tion # 2 & 3	
NS 2002 NOV 2009		1000				
Building Permit N	umber: B	& B:	ē			
Tests Performed:	Biorete	ntion Construct	tion: Visual Observation			
Problems/Non-Co	mpliances	s/Failing Tests:	Yes □ No 🗵	(if yes, detail	within Inspection Finding	s below)
			INSPECTION	FINDINGS:		
Caratina 40 - CE	I be a star				#3. The pond extends fro	
					VC pipe was laid and abou	
					VDOT #57 stones. No bid ting bioretention #2 and	
the excavated dirt		actor moved to	backilli the solid 6-inch	PVC pipe connec	ting bioretention #2 and	bioretention #5 with
the encoroted dire						
A COUNTY OF THE PARTY OF THE PA	The second secon				contractor identified, form	
					ative do not relieve the co	
					ite safety and the method geotechnical engineering	
			as to the professional ser		a geoteen mear engineering	g practices. We make
The College of the Co						
			professional engineer. A	any conclusions dr	rawn from this report sho	uld be discussed with
the professional e	ngineer in	volved.				
THE RESERVE AND ADDRESS OF THE PARTY OF THE		the state of the s			eld representative and is s itute a certification. Appr	A CONTRACTOR OF THE PARTY OF TH
		The second secon			ed on this data are the res	
Time of	Arrival:	9:30 AM	Time of Departure:	5:00 PM	Total Time Onsite:	7.50
					Lab Time:	8
<u>53</u>	32			_	Other ():	
	narge:*		Mileage:*		Travel Time*:	2.00
*will b	e billed in	n accordance	with contract	(4)	Total Time:	9.50
						-70




Tree Filter #3 excavation



Tree Filter #3 #57 stone depth, 9"


Project Name:	SWM ID: 2	
	Date:	
Project No.:	Prepared By:	
	Scale: As Shown □ Not to Scale ☑	







#8 stone installed in Tree Filter #2, 3"



Description of Work: Location:	Project: Location: Client Name: Contractor:				Repr	Day & Date: Project#: resentative: emp Range: Weather:	
Building Permit Number: B Tests Performed: Bioretention Construction: Visual Observation Problems/Non-Compliances/Failing Tests: Yes □ No ☒ (if yes, detail within Inspection Findings below) INSPECTION FINDINGS: Tepresentative observed and monitored finishing the bioretention # 3 installation. The contractor finish installing the bioretention #3 by placing the rest of the bio media up to 4 ft. The contractor also installed the drainage pipe up to the manhole. The placement of bio media and the drainage pipe installation observed today appeared to be in accordance with the project plans and specifications. The professional engineer is represented on site solely to observe operations of the contractor identified, form opinions and report those opinions to the client. The presence and activities of the engineer's representative do not relieve the contractor's obligation to meet contractual requirements. The contractor retains sole responsibility for site safety and the methods and sequence of construction. We have performed our services in accordance with generally accepted geotechnical engineering practices. We make no warranty; either expressed or implied, as to the professional services provided. This report is the instrument of service of a professional engineer. Any conclusions drawn from this report should be discussed with the professional engineer involved. This report constitutes a summary of observations and tests performed by our field representative and is subject to review and revision by our managers and engineers. The statements made herein do not constitute a certification. Approval of work for final acceptance can only be made by our managers and engineers. Interpretations based on this data are the responsibility of others. Time of Arrival: 8:00 AM Time of Departure: 04:45 PM Total Time Onsite: 8.75 Lab Time: Other (): Trip Charge:* Mileage:* Trip Charge:* Mileage:*							
Problems/Non-Compliances/Failing Tests: Yes No (if yes, detail within Inspection Findings below) INSPECTION FINDINGS: representative observed and monitored finishing the bioretention #3 installation. The contractor finish installing the bioretention #3 by placing the rest of the bio media up to 4 ft. The contractor also installed the drainage pipe up to the manhole. The placement of bio media and the drainage pipe installation observed today appeared to be in accordance with the project plans and specifications. The professional engineer is represented on site solely to observe operations of the contractor identified, form opinions and report those opinions to the client. The presence and activities of the engineer's representative do not relieve the contractor's obligation to meet contractual requirements. The contractor retains sole responsibility for site safety and the methods and sequence of construction. We have performed our services in accordance with generally accepted geotechnical engineering practices. We make no warranty; either expressed or implied, as to the professional services provided. This report is the instrument of service of a professional engineer. Any conclusions drawn from this report should be discussed with the professional engineer involved. Please see the attached pictures of work in the following pages: This report constitutes a summary of observations and tests performed by our field representative and is subject to review and revision by our managers and engineers. The statements made herein do not constitute a certification. Approval of work for final acceptance can only be made by our managers and engineers. Interpretations based on this data are the responsibility of others. Time of Arrival: 8:00 AM Time of Departure: 04:45 PM Total Time Onsite: 8.75 Lab Time: Other (): Travel Time*: 2.00					Urban bioretenti	on # 2 & 3	
representative observed and monitored finishing the bioretention #3 installation. The contractor finish installing the bioretention #3 by placing the rest of the bio media up to 4 ft. The contractor also installed the drainage pipe up to the manhole. The placement of bio media and the drainage pipe installation observed today appeared to be in accordance with the project plans and specifications. The professional engineer is represented on site solely to observe operations of the contractor identified, form opinions and report those opinions to the client. The presence and activities of the engineer's representative do not relieve the contractor's obligation to meet contractual requirements. The contractor retains sole responsibility for site safety and the methods and sequence of construction. We have performed our services in accordance with generally accepted geotechnical engineering practices. We make no warranty; either expressed or implied, as to the professional services provided. This report is the instrument of service of a professional engineer. Any conclusions drawn from this report should be discussed with the professional engineer involved. This report constitutes a summary of observations and tests performed by our field representative and is subject to review and revision by our managers and engineers. The statements made herein do not constitute a certification. Approval of work for final acceptance can only be made by our managers and engineers. Interpretations based on this data are the responsibility of others. Time of Arrival: 8:00 AM Time of Departure: 04:45 PM Total Time Onsite: 8.75 Lab Time: Other (): Travel Time*: 2.00	Tests Performed:	Biorete	ntion Construct	tion: Visual Observation			
representative observed and monitored finishing the bioretention #3 installation. The contractor finish installing the bioretention #3 by placing the rest of the bio media up to 4 ft. The contractor also installed the drainage pipe up to the manhole. The placement of bio media and the drainage pipe installation observed today appeared to be in accordance with the project plans and specifications. The professional engineer is represented on site solely to observe operations of the contractor identified, form opinions and report those opinions to the client. The presence and activities of the engineer's representative do not relieve the contractor's obligation to meet contractual requirements. The contractor retains sole responsibility for site safety and the methods and sequence of construction. We have performed our services in accordance with generally accepted geotechnical engineering practices. We make no warranty; either expressed or implied, as to the professional services provided. This report is the instrument of service of a professional engineer. Any conclusions drawn from this report should be discussed with the professional engineer involved. This report constitutes a summary of observations and tests performed by our field representative and is subject to review and revision by our managers and engineers. The statements made herein do not constitute a certification. Approval of work for final acceptance can only be made by our managers and engineers. Interpretations based on this data are the responsibility of others. Time of Arrival: 8:00 AM Time of Departure: 04:45 PM Total Time Onsite: 8.75 Lab Time: Other (): Travel Time*: 2.00	Problems/Non-Com	pliances	/Failing Tests:	Yes □ No 🏻	(if yes, detail v	vithin Inspection Findings b	elow)
installing the bioretention #3 by placing the rest of the bio media up to 4 ft. The contractor also installed the drainage pipe up to the manhole. The placement of bio media and the drainage pipe installation observed today appeared to be in accordance with the project plans and specifications. The professional engineer is represented on site solely to observe operations of the contractor identified, form opinions and report those opinions to the client. The presence and activities of the engineer's representative do not relieve the contractor's obligation to meet contractual requirements. The contractor retains sole responsibility for site safety and the methods and sequence of construction. We have performed our services in accordance with generally accepted geotechnical engineering practices. We make no warranty; either expressed or implied, as to the professional services provided. This report is the instrument of service of a professional engineer. Any conclusions drawn from this report should be discussed with the professional engineer involved. Please see the attached pictures of work in the following pages: This report constitutes a summary of observations and tests performed by our field representative and is subject to review and revision by our managers and engineers. The statements made herein do not constitute a certification. Approval of work for final acceptance can only be made by our managers and engineers. Interpretations based on this data are the responsibility of others. Time of Arrival: 8:00 AM Time of Departure: 04:45 PM Total Time Onsite: 8.75 Lab Time: Other (): Travel Time*: 2.00	o.			INSPECTION F	INDINGS:		
revision by our managers and engineers. The statements made herein do not constitute a certification. Approval of work for final acceptance can only be made by our managers and engineers. Interpretations based on this data are the responsibility of others. Time of Arrival: 8:00 AM Time of Departure: 04:45 PM Total Time Onsite: 8.75 Lab Time: Other (): Trip Charge:* Mileage:* 2.00	the manhole. The p the project plans are The professional engopinions to the clien contractual requirer have performed our expressed or implied This report is the ins professional engineer	dineer is a nt. The p nents. The services d, as to the strument er involve	t of bio media ications. represented on resence and ac ne contractor re in accordance ne professional : of service of a ed.	and the drainage pipe institution of the engineer's stains sole responsibility for with generally accepted gravices provided.	rations of the control representative do for site safety and to geotechnical engine	d today appeared to be in a actor identified, form opinio not relieve the contractor's he methods and sequence of eering practices. We make	ns and report those obligation to meet of construction. We no warranty; either
Lab Time: Other ():	revision by our ma	nagers a	nd engineers.	The statements made he	rein do not constit	tute a certification. Approv	al of work for final
Trip Charge:* Mileage:* Travel Time*: 2.00	Time of A	rrival:	8:00 AM	Time of Departure:	04:45 PM	Total Time Onsite:	8.75
Trip Charge:* Mileage:* Travel Time*: 2.00					•		
	Tain Ob a	***		Milenge:*	7		2.00
		$\overline{}$	n accordance				1 100 000





First 2 feet of soil media installed in Tree Filter #2



4 feet of soil media installed in Tree Filter #2

Project Name:	SWM ID: 2 & 3		
	Date:		
Project No.:	Prepared By:		
	Scale: As Shown ☐ Not to Scale ☒		
	Project No.:		







4 feet of soil media installed in Tree Filter #3

Project Name:

Date:

Project No.:

Prepared By:

Scale: As Shown □ Not to Scale ☑

Certification Letter for Proprietary BMP



April 6, 2022

Stormwater Specialist Department of Environmental Services 2100 Clarendon Blvd Suite 705 Arlington, VA 22201

RE: Stormwater Management Facility (SWMF) As-Built Certification

, LDA#

Dear Sir or Madam.

BUILDING PERMIT #

We have inspected the **Contech Jellyfish JF4-1-1** facility that was constructed as part of the above referenced project and determined that it has been installed in accordance to the County approved plan dated manufactured stormwater filtration facility is comprised of a **Contech JellyFish JF4-1-1** system including 1-27" **Hi-Flo Cartridge, 1-27" Drawdown Cartridge, and 1 Cartridge Blank** that treats stormwater runoff for this project.

Based on the as-built conditions of the site, the **JF4-1-1** facility treats **0** acres of which **0** acres is impervious, therefore the facility meets the requirements of the Arlington County's Stormwater Ordinance.

For reference, the as-built drawings are attached showing the sizing of the facility along with the activation letter from the manufacturer. As required, the as-built drawings include the inverts for all inflow/outfall pipes connected to the facility. Therefore, it is our professional opinion that the facility was installed in accordance to the County approved plan and that the facility is functioning as designed.

If you have any questions regarding the above-mentioned facility, please do not hesitate to call me.

Respectfully,



Attachments:

- 1. As-built drawings
- 2. Activation Letter from manufacturer



Contech Engineered Solutions LLC 9025 Centre Pointe Drive, Suite 400 West Chester, OH 45069 Phone: (513) 645-7000

Phone: (513) 645-7000 www.ContechES.com

Contech Activation Letter - Jellyfish



March 28, 2022

Project#

Project Name:

Project Jurisdiction: Arlington, VA

Hello,

This 2 page letter should be used as official notification to your local jurisdiction with regard to the activation of your Jellyfish Systems.

Please be advised that after installation (not by Contech), the Jellyfish stormwater treatment units were activated on Activation refers to bringing the unit into operation by installing the filter cartridges.

The second page of this letter contains a list of each Jellyfish unit that is covered by this activation letter.

Please feel free to contact me if any additional information is needed.

Sincerely,

Activation and Maintenance Coordinator Contech Engineered Solutions, LLC



Contech Engineered Solutions LLC 9025 Centre Pointe Drive, Suite 400 West Chester, OH 45069 Phone: (513) 645-7000

www.ContechES.com

Contech Activation Letter - Jellyfish

Contech hereby confirms that the following units were supplied to the subject project as per the approved plans:

Unit # JF JF4-1-1 * 1 (27" High Flow) 1 (27" Drain Down) 1 (Empty - Blank) Installed


Certification Letter for Water Quantity Control (Detention) Facility



February 16, 2021

Stormwater Specialist Department of Environmental Services 2100 Clarendon Blvd Suite 705 Arlington, VA 22201

RE: Stormwater Management Facility (SWMF) Certification



Dear Sir or Madam.

A stormwater detention facility was required as part of the above referenced project dated detention facility is comprised of a 100' long 48" CMP pipe (1,257 CF) that provides stormwater runoff quantity control for this project.

Based on the constructed conditions of the site, facility SWM-1 captures and controls 0.966 Acres of which 0.79 Acres is impervious.

For reference, the record drawings are attached showing the sizing of the facility. As required, the attached drawings include, but are not limited to, the following information: inner dimensions of the facility (L x W x H); dimensions of any internal chambers (i.e. clearwell); trash rack details; sizes and inverts for all orifices, weirs, and inflow/outfall pipes.

Pursuant to 9VAC25-870-55 and Arlington County Code Chapter 60-8, I hereby certify that to the best of my knowledge and belief the stormwater management facilities shown on these record drawings have been constructed in accordance with the approved plans and specifications.

Name	Signature
Virginia License	Date

"Certify means to state or declare a professional opinion based on sufficient and appropriate onsite inspections, material tests, as-built survey data, and information provided by other professionals and the contractor, conducted during or after construction."

Enclosure:

1. Record drawings