

Arlington Forest Branch Retrofits Ranking Summary (Arranged by Rank)				
Site ID	Site Description	Practice	Score	Rank
AF_116	Arlington Assembly of God - parking lot and trailer storage lot	Disconnection	79.30	1
AF_595B	1st Street N. & N. Wakefield St	Street Bioretention	53.45	2
AF_591A	Intersection of North Wakefield St and 2nd St N	Street Bioretention	47.96	3
AF_591C	Intersection of North Wakefield St and 2nd St N	Street Bioretention	44.99	4
AF_591B	Intersection of North Wakefield St and 2nd St N	Street Bioretention	43.24	5
AF_694A	118 North Abingdon Street	Street Bioretention	41.26	6
AF_694B	121 North Abingdon Street	Street Bioretention	39.92	7
AF_591D	Intersection of North Wakefield St and 2nd St N	Street Bioretention	36.06	8
AF_698A	416 South Abingdon Street	Street Bioretention	30.31	9
AF_595A	1st Street N. & N. Wakefield St	Street Bioretention	24.40	10
AF_698B	417 South Abingdon Street	Street Bioretention	22.11	11