Bailey's Branch Retrofits Ranking Summary (Arranged by Rank)					
Site ID	Site Description	Practice	Score	Rank	
BB_223	990 South Columbia Street	Bioretention	94.62	1	
BB_226	5550 Columbia Pike	Bioretention	63.00	2	
BB_209	5228 8th Road South	Street Bioretention	40.51	3	
BB_718	871 South Greenbrier Street	Street Bioretention	38.00	4	
BB_717	851 South Greenbrier Street	Street Bioretention	35.95	5	
BB_238	5353 Columbia Pike	Bioretention	32.42	6	
BB_716	832 South Greenbrier Street	Street Bioretention	28.10	7	
BB_239	851 South Frederick Street	Bioretention	27.02	8	
BB_211B	5316 8th Road South	Bioretention	26.20	9	
BB_222	955 South Columbia Street	Bioretention	22.83	10	
BB_212A	5100 Columbia Pike	Bioretention	16.13	11	
BB_212B	5100 Columbia Pike	Bioretention	15.01	12	
BB_211A	5314 8th Road South	Rain garden	14.66	13	

Bailey's Branch Retrofits - Unranked Projects					
Site ID	Site Description	Practice	Score		
Sites with <.25 acres of contributing drainage area					
BB_210	804 8th Road South	Bioretention	14.31		
BB_211C	5314 8th Road South	Disconnection	24.95		
Concepts that treat < 10% Tv					
BB_715	756 8th Road South	Street Bioretention	52.35		